

Product Discontinuation



PD_039_17

■ Last Order Date:	2017-09-30
■ Last Delivery Date:	2018-03-31

Reason: Assembly location Malacca will be shifted to Amkor Philippines for the above mentioned product”
From April 2018 only Amkor Philippines available

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
SAL-XC866L-4FRA 5V BE	SP000876778	XC866L4FRA5VBELXUMA1	PG-TSSOP-38	SAL-XC866L-4FRA 5V BE	SP001691994	N.A.	PG-TSSOP-38

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!