



Product Change Notification

TE Connectivity

Product Change Notification: P-22-022188

PCN Date: 17-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Spec 44 and FLDW Wires

Description of Changes
TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 44 and FLDW Wires. This change is to an alternate grade with similar performance and characteristics.

Reason for Changes:
Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	28-MAR-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282000-015	NO			"3-1192090-0", "44A0111-16-0-MX"			
282002-014	NO			"6-1192090-6", "44A0111-16-2-MX"			
282011-010	NO			"1192092-9", "44A0111-18-1-US"			
282020-018	NO			"6-1192093-2", "44A0111-20-0-MX"			
282022-026	NO			"1-1192094-5", "44A0111-20-2-MX"			
306045-001	NO			"3-1192317-9", "44AM1121-20-0/9-9"			
382243-015	NO			"6-1192858-9", "44A1121-24-0/9-9-MX"			
382254-009	NO			"1-1192859-1", "44A1121-22-0/9-9-MX"			
382286-000	NO			"6-1192859-7", "44A1121-22-2/6-9-MX"			
382315-002	NO			"4-1192861-4", "44A0121-22-6/9-MX"			
382394-003	NO			"7-1192862-3", "44A1141-22-0/2/6/9-9"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282000-015	NO			"3-1192090-0", "44A0111-16-0-MX"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282000-015	NO			"3-1192090-0", "44A0111-16-0-MX"			
282002-014	NO			"6-1192090-6", "44A0111-16-2-MX"			
282011-010	NO			"1192092-9", "44A0111-18-1-US"			
282020-018	NO			"6-1192093-2", "44A0111-20-0-MX"			
282022-026	NO			"1-1192094-5", "44A0111-20-2-MX"			
306045-001	NO			"3-1192317-9", "44AM1121-20-0/9-9"			
382243-015	NO			"6-1192858-9", "44A1121-24-0/9-9-MX"			
382254-009	NO			"1-1192859-1", "44A1121-22-0/9-9-MX"			
382286-000	NO			"6-1192859-7", "44A1121-22-2/6-9-MX"			
382315-002	NO			"4-1192861-4", "44A0121-22-6/9-MX"			
382394-003	NO			"7-1192862-3", "44A1141-22-0/2/6/9-9"			