

Product Change Notification 32702 is complete and has been sent to approved customers. Please e-mail [QA\\_PCN\\_SUPPORT@micron.com](mailto:QA_PCN_SUPPORT@micron.com) if you have any questions regarding this Product Change Notification.



Micron Technology, Inc.  
8000 S. Federal Way  
PO Box 6  
Boise, ID United States

---

## J55U 8GB Auto eMMC v4.41 End of Life for selected Material Part Numbers

PCN: 32702

Published: 2018-04-30

---

**Type:** End of Life

---

**Description:** 8GB J55U Auto eMMC v4.41 Material Part Numbers (MTFC8GLWDM-3M AIT Z; MTFC8GLWDQ-3L AITI Z; MTFC8GLWDM-3L AAT Z) will end of life. All other J55U Material part numbers will remain available.

---

**Reason:** Change in Market Demand

---

**Product Affected:** Selected J55U Auto eMMC v4.41 Material Part Numbers (MTFC8GLWDM-3M AIT Z; MTFC8GLWDQ-3L AITI Z; MTFC8GLWDM-3L AAT Z)

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>Component</u>		
MTFC8GLWDM-3L AAT Z		
MTFC8GLWDM-3M AIT Z		
MTFC8GLWDQ-3L AITI Z		

\*Materials that have been ordered are in **bold**.

---

**Method of Identification:** Material Part Number

---

<b>Micron Sites Affected:</b>	All Sites
<b>Last Purchase Date*:</b>	2018-10-30
<b>Last Shipment Date:</b>	2019-04-30

---

\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**Micron Confidential and Proprietary Information**

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.