

Attn.: _____

HIROSE ELECTRIC CO., LTD.
5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

Notice of Plan Change for Additional Production at Indonesian Plant
for Products Produced at Malaysian Plant
and Request for Your Acknowledgement

Hirose would like to take this opportunity to thank you sincerely for your support, and we hope this letter finds you well and prosperous.

In August 2015 we notified you of additional production at Indonesian Plant for products produced at Malaysian Plant (Notice: Business 430-15050). However, we are writing today to inform you that the additional production at Indonesian Plant will be partly cancelled.

We sincerely apologize for any inconvenience this may cause.

We request that you kindly offer your consent to this matter.

1. Product Series Affected by Cancellation of Additional Production

Series	Timing of additional production at Indonesian Plant	
	Previous Notice	After Change
FX8C	From January 2016	Cancelled
HIF6	From January 2016	Cancelled
TM	From January 2016	Cancelled

See the attached list of products affected.

2. Reasons for Change

Due to a change in our production plan.

3. Items Related to Products to be Delivered

Malaysian Plant will continue to handle these products by giving instructions from production to shipment.

Please feel free to contact a Hirose account representative if you have any questions.

[Attachment] List of Products Affected by Cancellation of Additional Production

(excerpt from operating 430-15050 written product list issued August 2015)

No.	CL CODE	Product Name		No.	CL CODE	Product Name
1	CL578-0601-3 80	FX8C-60P-SV6(80)	※	53	CL222-1467-9 50	TM2REA-0606(50)
2	CL578-1003-7 00	FX8CS-140P-SV6	※	54	CL222-0802-6 50	TM2REA-1204(50)
3	CL578-1003-7 86	FX8CS-140P-SV6(86)	※	55	CL222-0799-3 50	TM2REA-1208(50)
4	CL578-1004-0 00	FX8CS-140S-SV5	※	56	CL222-3821-7 50	TM2REA-1210-64(50)
5	CL578-1004-0 84	FX8CS-140S-SV5(84)	※	57	CL222-0681-3 50	TM2REA-1212(50)
6	CL630-0011-8 00	HIF6-100D-1.27R	※	58	CL222-0801-3 50	TM2REA-1806(50)
7	CL630-0011-8 02	HIF6-100D-1.27R(02)	※	59	CL222-0798-0 50	TM2REA-1812(50)
8	CL630-0011-8 05	HIF6-100D-1.27R(05)	※	60	CL222-0737-6 50	TM2REA-1818(50)
9	CL630-0001-4 00	HIF6-20D-1.27R	※	61	CL222-0800-0 50	TM2REA-2408(50)
10	CL630-0002-7 00	HIF6-26D-1.27R	※	62	CL222-0749-5 50	TM2REA-2416(50)
11	CL630-0003-0 00	HIF6-32D-1.27R	※	63	CL222-0750-4 50	TM2REA-2424(50)
12	CL630-0004-2 00	HIF6-34D-1.27R	※	64	CL222-5018-7 50	TM2REAX-1204(50)
13	CL630-0004-2 02	HIF6-34D-1.27R(02)	※	65	CL222-5024-0 50	TM2REAX-2408(50)
14	CL630-0005-5 00	HIF6-40D-1.27R	※	66	CL222-5025-2 65	TM2REAX-2416(65)
15	CL630-0006-8 00	HIF6-50D-1.27R	※	67	CL222-1012-9 50	TM3RA-88(50)
16	CL630-0006-8 02	HIF6-50D-1.27R(02)	※	68	CL222-1012-9 55	TM3RA-88(55)
17	CL630-0006-8 05	HIF6-50D-1.27R(05)	※	69	CL222-1012-9 58	TM3RA-88(58)
18	CL630-0007-0 00	HIF6-52D-1.27R	※	70	CL222-5034-3 50	TM3RAX-88(50)
19	CL630-0008-3 00	HIF6-60D-1.27R	※	71	CL222-5047-5 50	TM5RBX-66-2.5DS(50)
20	CL630-0008-3 05	HIF6-60D-1.27R(05)	※	72	CL222-1513-4 50	TM5RC-1212(50)
21	CL630-0009-6 00	HIF6-68D-1.27R	※	73	CL222-1513-4 51	TM5RC-1212(51)
22	CL630-0009-6 02	HIF6-68D-1.27R(02)	※	74	CL222-2578-5 50	TM5RC-1212-1.2(50)
23	CL630-0010-5 00	HIF6-80D-1.27R	※	75	CL222-0270-9 50	TM5RC-44(50)
24	CL630-0010-5 02	HIF6-80D-1.27R(02)	※	76	CL222-0338-0 50	TM5RC-64(50)
25	CL630-0010-5 05	HIF6-80D-1.27R(05)	※	77	CL222-0337-8 50	TM5RC-66(50)
26	CL222-2850-0 50	TM1 1R-5C-62(50)		78	CL222-0339-3 50	TM5RC-88(50)
27	CL222-2148-6 50	TM1 1R-5C-66(50)		79	CL222-5136-3 20	TM5RE3VX-1212(20)
28	CL222-1378-0 50	TM1 1R-5C-88(50)		80	CL222-1242-9 71	TM5RF1-44(71)
29	CL222-5133-5 50	TM1 1RX-5C-88(50)		81	CL222-5002-7 50	TM5RFX-44(50)
30	CL222-2981-8 00	TM24P-HR1-88(4)P1-TL		82	CL222-1459-0 50	TM5RJ2-44(50)
31	CL222-2971-4 00	TM24P-HR1-88(4)P-TL		83	CL222-1486-3 50	TM5RJ2-62(50)
32	CL222-2959-9 00	TM24P-HR1-88P-TL		84	CL222-1486-3 90	TM5RJ2-62(90)
33	CL299-8006-0 00	TM24P-HR1-88P-TL-1		85	CL222-1460-0 50	TM5RJ2-64(50)
34	CL222-2960-8 00	TM24P-HR2-88P-TL		86	CL222-1460-0 52	TM5RJ2-64(52)
35	CL222-2972-7 00	TM24P-HR3-88(4)P-TL		87	CL222-1461-2 50	TM5RJ2-66(50)
36	CL222-2961-0 00	TM24P-HR3-88P-TL		88	CL222-1461-2 52	TM5RJ2-66(52)
37	CL222-2962-3 00	TM24P-HR-SHE1		89	CL222-1461-2 53	TM5RJ2-66(53)
38	CL222-2963-6 00	TM24P-HR-SHE2		90	CL222-1462-5 50	TM5RJ2-88(50)
39	CL222-1286-4 50	TM2RE-0602(50)		91	CL222-5081-3 50	TM5RJ2X-66(50)
40	CL222-1391-9 50	TM2RE-0604(50)		92	CL222-5081-3 53	TM5RJ2X-66(53)
41	CL222-1422-0 50	TM2RE-0606(50)		93	CL222-5082-6 50	TM5RJ2X-88(50)
42	CL222-0592-5 50	TM2RE-1204(50)		94	CL222-1363-3 50	TM5RJ3-44(50)
43	CL222-0756-0 50	TM2RE-1208(50)		95	CL222-1487-6 50	TM5RJ3-62(50)
44	CL222-0757-3 50	TM2RE-1212(50)		96	CL222-1463-8 50	TM5RJ3-64(50)
45	CL222-0591-2 50	TM2RE-1806(50)		97	CL222-1464-0 50	TM5RJ3-66(50)
46	CL222-0753-2 50	TM2RE-1812(50)	※	98	CL222-1464-0 51	TM5RJ3-66(51)
47	CL222-0796-5 50	TM2RE-1818(50)		99	CL222-1465-3 50	TM5RJ3-88(50)
48	CL222-0797-8 50	TM2RE-2408(50)		100	CL222-1465-3 51	TM5RJ3-88(51)
49	CL222-0590-0 50	TM2RE-2416(50)		101	CL222-1465-3 52	TM5RJ3-88(52)
50	CL222-0751-7 50	TM2RE-2424(50)		102	CL222-5085-4 50	TM5RJ3X-64(50)
51	CL222-1277-3 50	TM2REA-0602(50)		103	CL222-5087-0 50	TM5RJ3X-88(50)
52	CL222-1466-6 50	TM2REA-0604(50)				

A product with※ has finished selling it to the right side of the product name present.

Acknowledgment

(Customer -> Hirose Electric business representative)

**Notice of Plan Change for Additional Production at Indonesian Plant
for Products Produced at Malaysian Plant
and Request for Your Acknowledgement**

We acknowledge the aforementioned matter.

●Customer's name: _____

●Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.

_____ (Cut on this line) _____

Document Receipt

(Customer -> Hirose Electric business representative)

**Notice of Plan Change for Additional Production at Indonesian Plant
for Products Produced at Malaysian Plant
and Request for Your Acknowledgement**

We received the document concerning the above.

●Customer's name: _____

●Acknowledgment stamp (or signature): _____

HIROSE ELECTRIC CO., LTD.