



Product Change Notice

Micron PCN: 31566
 Date: 5/28/2015

Type of Change:	Manufacturing Site – Change or Addition		
Title of Change:	65nm (P806) Process Transfer from Israel (Fab12) to Singapore (Fab13) – QKHP, QKGP, QKFP		
Description of Change:	Fabrication of Micron’s 128Mb 65nm P806 (QKHP), 64Mb 65nm P806 (QKGP), and 32Mb 65nm P806 (QKFP) products are transferring from Israel (Fab12) to Singapore (Fab13). The transfer enables long- term support and focus on Micron’s commitment to NOR technology. Devices produced in Fab13 are form, fit, and functionally equivalent to those devices produced in Fab12. The design and manufacturing process have been transferred from Fab12 to Fab13 to enable the production of identical products.		
Reason for Change:	Manufacturing Efficiency		
Contact Information:	<u>AMERICAS</u> JOHN VOTINO JJVOTINO@MICRON.COM <u>ASIA-PACIFIC</u> JINGWEN YANG JYANG@MICRON.COM	<u>JAPAN</u> DAIGO TOYAMA DTOYAMA@MICRON.COM <u>EMEA</u> RICCARDO TOLLER RTOLLER@MICRON.COM	

- Product Affected:** 65nm (P806) Parallel NOR Flash Memory:
- 128Mb 65nm (QKHP) – M29EW, P30, P33, J3
 - 64Mb 65nm (QKGP) – M29EW, P30, P33, J3
 - 32Mb 65nm (QKFP) – J3

Affected Micron Part Number

128Mb – QKHP

JS28F128M29EWHF	JS28F128P30BF75A	JS28F128P33BF70A	PC28F128J3F75A
JS28F128M29EWLA	JS28F128P30TF75A	JS28F128P33TF70A	PC28F128J3F75B
PC28F128M29EWHF	PC28F128P30BF65A	PC28F128P33BF60A	PC28F128J3F75D
PC28F128M29EWHG	PC28F128P30BF65E	PC28F128P33BF60D	RC28F128J3F75A
PC28F128M29EWHX	PC28F128P30TF65A	PC28F128P33TF60A	RC28F128J3F75B
PC28F128M29EWLA	PF48F3000P0ZBQEA	JS28F128J3F75A	RC28F128J3F75G
PC28F128M29EWLX	PF48F3000P0ZTQEA	JS28F128J3F75B	
PN28F128M29EWHA	RC28F128P30BF65A	JS28F128J3F75G	

64Mb – QKGP

JR28F064M29EWBA	PC28F064M29EWHA	JS28F640P30BF75A	JS28F640J3F75A
JR28F064M29EWHA	PC28F064M29EWHF	JS28F640P30TF75A	JS28F640J3F75B
JR28F064M29EWLA	PC28F064M29EWHX	PC28F640P30BF65A	JS28F640J3F75E
JR28F064M29EWTA	PC28F064M29EWLA	PC28F640P30BF65B	JS28F640J3F75G
JR28F064M29EWTB	PC28F064M29EWTA	PC28F640P30TF65A	PC28F640J3F75A
JS28F064M29EWBA	PC28F064M29EWTY	PC28F640P30TF65B	PC28F640J3F75B
JS28F064M29EWHA	PZ28F064M29EWBA	JS28F640P33BF70A	RC28F640J3F75A
JS28F064M29EWLA	PZ28F064M29EWHA	JS28F640P33TF70A	RC28F640J3F75B
JS28F064M29EWTA	PZ28F064M29EWLA	PC28F640P33BF60A	
PC28F064M29EWBA	PZ28F064M29EWTA	PC28F640P33TF60A	

Note: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change



Affected Micron Part Number

32Mb – QKFP

JS28F320J3F75A	JS28F320J3F75E	PC28F320J3F75A	PC28F320J3F75E
JS28F320J3F75B	JS28F320J3F75F	PC28F320J3F75B	

Method of Identification:

Packing container label: the inner packing container label will change from "Fab12" (Israel) to "Fab13" (Singapore). Please refer to Micron Customer Service Note-11 for detailed description of inner packing container label.

Micron Sites Affected: Fab12 – ISR
Fab13 – SG

Product/Data Schedule

New/Changed Product:

Sample Availability:	Now
Qual Data Availability:	Now
Ready to Receive:	11/30/2015
