

# PRODUCT CHANGE NOTIFICATION

Product Category COPPER - CABLE - 10G 20220722

Product Group COPPER CABLE

ISSUE DATE: 20220503

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Summary - As a result of rationalization and simplification of the Panduit Copper Cable Portfolio, we have consolidated product families. Please review the product notification for a list of the effected parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	7	22

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	Type	Replacement Part 1	Replacement Part 2	Replacement Part 3
PURCA6C04BU-UG	No Replacement			
PURCA26C04BU-UG	No Replacement			
PSP6X04BL-UG	Direct Replacement	PUFP6X04BL-UG		
PSP6X04BU-UG	Direct Replacement	PUFP6X04BU-UG		
PSP6X04IG-UG	Direct Replacement	PUFP6X04IG-UG		
PSP6X04GR-UG	Direct Replacement	PUFP6X04GR-UG		
PSP6X04RD-UG	Direct Replacement	PUFP6X04RD-UG		
PSP6X04OR-UG	Direct Replacement	PUFP6X04OR-UG		
PSP6X04VL-UG	Direct Replacement	PUFP6X04VL-UG		
PSP6X04WH-UG	Direct Replacement	PUFP6X04WH-UG		
PSP6X04YL-UG	Direct Replacement	PUFP6X04YL-UG		