



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000868

DATE: 10-May-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG300AC/D	N/A	10-May-2019	09-Nov-2019	Part is leaded. Request information on lead-free version
Discontinuance	DG411C/D	N/A	10-May-2019	09-Nov-2019	Part is leaded. Request information on lead-free version
Discontinuance	HI1-0508A-2	N/A	10-May-2018	10-May-2018	Part is leaded. Request information on lead-free version
Discontinuance	HI3-0508A-5+	N/A	10-May-2018	10-May-2018	Part can no longer be manufactured
Discontinuance	IH5143C/D	IH5143CPE+	10-May-2018	10-May-2018	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX20077ATCEX/VY+	N/A	10-May-2018	10-May-2018	The part was not released
Discontinuance	MAX4579CPP+	N/A	10-May-2019	09-Nov-2019	Part can no longer be manufactured
Discontinuance	MAX4800ACQI+	N/A	10-May-2019	09-Nov-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 10-Jun-2018