



Product Change Notification

TE Connectivity

Product Change Notification: E-19-010675

PCN Date: 12-JUL-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DEUTSCH DT, DTP Wedges and HDP Backshells Manufacturing Location Change

Description of Changes
The Industrial and Commercial Transportation business unit of TE Connectivity is transferring the production of the part numbers listed below from TE Hemet/CA-USA to TE Tullahoma/TN-USA or TE externally approved supplier. Shipping point will change from Ontario, CA, USA to Greensboro, NC, USA. These PN's are TE proprietary designs, therefore considered catalog/general market product. Tools that manufacture parts within this PCN are identified as "swing tool" and TE reserves the right in future to move tool to a TE ICT Manufacturing location and/or a TE externally approved supplier as needed. In case of subsequent transfer of swing tool, PCN will be sent to notify but will have a zero day wait period. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or TE e-PPAP system. Submissions will not occur without request. If PPAP is requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:
This change is necessary for alignment of overall manufacturing capacity and footprint to better meet our Customer's needs. IMPORTANT: The change will not impact fit, form or function.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	12-SEP-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	12-SEP-2024

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2428-008-2405	NO			"ZPF00000000131576", "2428-008-2405-AS", "2428-008-2405-LD", "2428-008-2405-MS", "2428-008-2405-L", "2428-008-2405-M"			
W12P	NO			"ZPF00000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF00000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF00000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF00000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2P-P004	NO			"W2P-P004-LD", "W2P-P004-MS", "W2P-P004-L", "W2P-P004-M"			
W2S	NO			"ZPF00000000131424"			
W2S-P012	NO			"ZPF00000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF00000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764"			
W3P-1939	NO			"ZPF00000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF00000000131437"			
W3S-1939-P012	NO			"ZPF00000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF00000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"ZPF00000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF00000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF00000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF00000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF00000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF00000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF00000000131459"			
W8S	NO			"ZPF00000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF00000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WP-2P	NO			"ZPF00000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF00000000131483"			
WP-4P	NO			"ZPF00000000131484"			
WP-4S	NO			"ZPF00000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			
Y2428-024-24050000	NO			"2428-024-2405"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2428-008-2405	NO			"ZPF00000000131576", "2428-008-2405-AS", "2428-008-2405-LD", "2428-008-2405-MS", "2428-008-2405-L", "2428-008-2405-M"			
W12P	NO			"ZPF00000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF00000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF00000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF00000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2P-P004	NO			"W2P-P004-LD", "W2P-P004-MS", "W2P-P004-L", "W2P-P004-M"			
W2S	NO			"ZPF00000000131424"			
W2S-P012	NO			"ZPF00000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF00000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764"			
W3P-1939	NO			"ZPF00000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF00000000131437"			
W3S-1939-P012	NO			"ZPF00000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF00000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF00000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF00000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W4S-ZZ	NO			"W4S", "ZPF00000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF00000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF00000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF00000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF00000000131459"			
W8S	NO			"ZPF00000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF00000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WP-2P	NO			"ZPF00000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF00000000131483"			
WP-4P	NO			"ZPF00000000131484"			
WP-4S	NO			"ZPF00000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2428-008-2405	NO			"ZPF00000000131576", "2428-008-2405-AS", "2428-008-2405-LD", "2428-008-2405-MS", "2428-008-2405-L", "2428-008-2405-M"			
W12P	NO			"ZPF00000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF00000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF00000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF00000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2P-P004	NO			"W2P-P004-LD", "W2P-P004-MS", "W2P-P004-L", "W2P-P004-M"			
W2S	NO			"ZPF00000000131424"			
W2S-P012	NO			"ZPF00000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF00000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764"			
W3P-1939	NO			"ZPF00000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF00000000131437"			
W3S-1939-P012	NO			"ZPF00000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF00000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF00000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF00000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF00000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF00000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF00000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF00000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF000000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WP-2P	NO			"ZPF000000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF000000000131483"			
WP-4P	NO			"ZPF000000000131484"			
WP-4S	NO			"ZPF000000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF000000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF000000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF000000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF000000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF000000000131424"			
W2S-P012	NO			"ZPF000000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF000000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764"			
W3P-1939	NO			"ZPF000000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF000000000131437"			
W3S-1939-P012	NO			"ZPF000000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF000000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF000000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF000000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF000000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF000000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF000000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF000000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF000000000131459"			
W8S	NO			"ZPF000000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF000000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WP-2P	NO			"ZPF000000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF000000000131483"			
WP-4P	NO			"ZPF000000000131484"			
WP-4S	NO			"ZPF000000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			
Y2428-024-24050000	NO			"2428-024-2405"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W2S	NO			"ZPF00000000131424"			
WP-4P	NO			"ZPF00000000131484"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
W12P	NO			"ZPF00000000131462", "W12P-AS", "W12P-P004-M"			
W12S	NO			"ZPF00000000131463", "W12S-AS"			
W12S-P012	NO			"ZPF00000000131464", "W12S-P012-AS", "W12S-P012-LD", "W12S-P012-LS", "W12S-P012-MS", "\$W12S-P012", "W12S-P012-E", "W12S-P012-L", "W12S-P012-M"			
W2P	NO			"ZPF00000000131419", "W2P-AS", "W2P-LD", "W2P-LS", "W2P-L", "8202612042", "43018-000"			
W2S	NO			"ZPF00000000131424"			
W2S-P012	NO			"ZPF00000000131425", "W2S-P012-AS", "W2S-P012-LD", "W2S-P012-LS", "W2S-P012-MS", "\$W2S-P012", "W2S-P012-E", "W2S-P012-L", "W2S-P012-M", "820P-37547"			
W3P	NO			"ZPF00000000131434", "W3P-AS", "W3P-LS", "\$W3P", "W3P-L", "8202608764"			
W3P-1939	NO			"ZPF00000000131435"			
W3S	NO			"W3S-AS"			
W3S-1939	NO			"ZPF00000000131437"			
W3S-1939-P012	NO			"ZPF00000000131438", "W3S-1939-P012-AS", "W3S-1939-P012-MS", "W3S-1939-P012-M", "7-1899794-6"			
W3S-P012	NO			"ZPF00000000131439", "W3S-P012-AS", "W3S-P012-LD", "W3S-P012-LS", "W3S-P012-MS", "\$W3S-P012", "W3S-P012-L", "W3S-P012-M"			
W4P	NO			"ZPF00000000131440", "W4P-AS", "820E-37523", "820P-37764", "4004200321", "C20490"			
W4S-P012	NO			"ZPF00000000131446", "W4S-P012-LS", "W4S-P012-MS", "W4S-P012-L", "W4S-P012-M"			
W4S-ZZ	NO			"W4S", "ZPF00000000131445", "W4S-AS", "8202606748"			
W6P	NO			"ZPF00000000131455", "W6P-AS", "\$W6P"			
W6S	NO			"ZPF00000000131456", "W6S-AS"			
W6S-P012	NO			"ZPF00000000131457", "W6S-P012-LD", "W6S-P012-LS", "W6S-P012-MS", "W6S-P012-L", "W6S-P012-M"			
W8P	NO			"ZPF00000000131459"			
W8S	NO			"ZPF00000000131460", "6-1899776-4"			
W8S-P012	NO			"ZPF00000000131461", "W8S-P012-AS", "W8S-P012-LD", "W8S-P012-LS", "W8S-P012-MS", "W8S-P012-L", "W8S-P012-M"			
WP-2P	NO			"ZPF00000000131482", "WP-2P-AS"			
WP-2S	NO			"ZPF00000000131483"			
WP-4P	NO			"ZPF00000000131484"			
WP-4S	NO			"ZPF00000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			
Y2428-024-24050000	NO			"2428-024-2405"			