

Product Discontinuation Notice


May, 2010

Discontinuation of CM relay (PCB)



1. Reason: Low market demand

2. Affected parts:

<p>CM relays</p> 	<p>PC board type</p>	<p>CM00-P-</p>
--	----------------------	----------------

3. Last time buy: End of August 2010

4. Substitution:

<p>CN-H relays CN-M relays</p>	<p>ACNH000 ACNM00000</p>
------------------------------------	------------------------------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1169)