

Product Status Change Notice

Crystal Unit: XRCGB_F_S series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.
This is the official notification that product status of XRCGB-F-S is changed to NRND tentatively.
Your understanding and support are highly appreciated.

1. Product Type, Detail for the change:

- **Product Type:**
Crystal Unit: XRCGB_F_S series

- **Contents**
Murata tentatively changed the product status to NRND. (Not Recommended for New Design)

- **Period:**
Until new design is released. (Scheduled in June 2022)

2. Reasons/Background:

It was confirmed there is a possibility for some parts of XRCGB-F-S to be out of aging spec.
We plan to implement new design which will be released in June, 2022.
Please refer to the attached documents for affected partnumbers.

3. Contact Window:

Please contact Murata Sales, Representative, or Distributor in your area if you have any questions or concerns.

Truly Yours. Thank you.
Takahiro Takagi
General Manager
Product Engineering Department, Functional Device Division
Murata Manufacturing Co., Ltd.

| Murata Part Number | Murata Part Number | Murata Part Number |
|-----------------------|-----------------------|-----------------------|
| XRCGB24M000F1SBAR0 | XRCGB26M000F1SADR0 | XRCGB37M400F1S2MR0 |
| XRCGB24M000F1SBBR0 | XRCGB26M000F1SAJR0 | XRCGB37M400F1S2NR0 |
| XRCGB24M000F1SBCR0 | XRCGB26M000F1SALR0 | XRCGB37M400F1S2PR0 |
| XRCGB24M000F1SBDR0 | XRCGB26M000F1SBAR0 | XRCGB37M400F1S2RR0 |
| XRCGB24M000F1SBJR0 | XRCGB26M000F1SBBR0 | XRCGB37M400F1S2SR0 |
| XRCGB24M000F1SBLR0 | XRCGB26M000F1SBCR0 | XRCGB37M400F1S2TR0 |
| XRCGB24M000FFS1AR0 | XRCGB26M000F1SBDR0 | XRCGB37M400F1S2UR0 |
| XRCGB24M000FFS1BR0 | XRCGB26M000F1SBJR0 | XRCGB37M400F1S2VR0 |
| XRCGB24M000FFS1BR0 | XRCGB26M000F1SBLR0 | XRCGB37M400F1S2XR0 |
| XRCGB24M000FFS1BR0 | XRCGB26M000F1SBLR0 | XRCGB37M400F1SBLR0 |
| XRCGB24M000FFS1CR0 | XRCGB32M000F1S1AR0 | XRCGB38M400F1S1AR0 |
| XRCGB24M000FFS1DR0 | XRCGB32M000F1S1AR0 | XRCGB38M400F1S1BR0 |
| XRCGB24M000FFS1JR0 | XRCGB32M000F1S1BR0 | XRCGB38M400F1S1CR0 |
| XRCGB24M000FFS1LR0 | XRCGB32M000F1S1BR0 | XRCGB38M400F1S1DR0 |
| XRCGB24M000FFS1LR0 | XRCGB32M000F1S1CR0 | XRCGB38M400F1S1JR0 |
| XRCGB24M000FFS2CR0 | XRCGB32M000F1S1CR0 | XRCGB38M400F1S1LR0 |
| XRCGB25M000F1SBAR0 | XRCGB32M000F1S1CR0 | XRCGB38M400F1S2AR0 |
| XRCGB25M000F1SBBR0 | XRCGB32M000F1S1DR0 | XRCGB38M400F1S2AR0 |
| XRCGB25M000F1SBCR0 | XRCGB32M000F1S1JR0 | XRCGB38M400F1S2FR0 |
| XRCGB25M000F1SBDR0 | XRCGB32M000F1S1LR0 | XRCGB38M400F1S2GR0 |
| XRCGB25M000F1SBJR0 | XRCGB32M000F1S2AR0 | XRCGB38M400F1S2GR0 |
| XRCGB25M000F1SBKR0 | XRCGB32M000F1S2AR0 | XRCGB38M400F1S2HR0 |
| XRCGB25M000F1SBLR0 | XRCGB32M000F1S2BR0 | XRCGB38M400F1S2JR0 |
| XRCGB25M000FFS1AR0 | XRCGB32M000F1S2BR0 | XRCGB38M400F1S2KR0 |
| XRCGB25M000FFS1BR0 | XRCGB32M000F1S2BR0 | XRCGB38M400F1S2LR0 |
| XRCGB25M000FFS1CR0 | XRCGB32M000F1S2CR0 | XRCGB38M400F1S2MR0 |
| XRCGB25M000FFS1DR0 | XRCGB32M000F1S2DR0 | XRCGB38M400F1S2NR0 |
| XRCGB25M000FFS1JR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2PR0 |
| XRCGB25M000FFS1LR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2QR0 |
| XRCGB26M000F1S1AR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2RR0 |
| XRCGB26M000F1S1BR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2SR0 |
| XRCGB26M000F1S1BR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2TR0 |
| XRCGB26M000F1S1CR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2UR0 |
| XRCGB26M000F1S1DR0 | XRCGB32M000F1S2JR0 | XRCGB38M400F1S2VR0 |
| XRCGB26M000F1S1JR0 | XRCGB32M000F1S2KR0 | XRCGB38M400F1S2WR0 |
| XRCGB26M000F1S1LR0 | XRCGB32M000F1SAAR0 | XRCGB38M400F1S3AR0 |
| XRCGB26M000F1S2AR0 | XRCGB32M000F1SABR0 | XRCGB38M400F1SBLR0 |
| XRCGB26M000F1S2AR0 | XRCGB32M000F1SACR0 | XRCGB40M000F1S1AR0 |
| XRCGB26M000F1S2AR0 | XRCGB32M000F1SADR0 | XRCGB40M000F1S1BR0 |
| XRCGB26M000F1S2AR0 | XRCGB32M000F1SAJR0 | XRCGB40M000F1S1CR0 |
| XRCGB26M000F1S2BR0 | XRCGB32M000F1SALR0 | XRCGB40M000F1S1DR0 |
| XRCGB26M000F1S2BR0 | XRCGB32M000F1SBAR0 | XRCGB40M000F1S1JR0 |
| XRCGB26M000F1S2BR0 | XRCGB32M000F1SBBR0 | XRCGB40M000F1S1LR0 |
| XRCGB26M000F1S2CR0 | XRCGB32M000F1SBCR0 | XRCGB40M000F1S1NR0 |
| XRCGB26M000F1S2DR0 | XRCGB32M000F1SBCR0 | XRCGB40M000F1S2AR0 |
| XRCGB26M000F1S2ER0 | XRCGB32M000F1SBDR0 | XRCGB40M000F1S2BR0 |
| XRCGB26M000F1S2ER0 | XRCGB32M000F1SBJR0 | XRCGB40M000F1S2BR0 |
| XRCGB26M000F1S2ER0 | XRCGB32M000F1SBLR0 | XRCGB40M000F1S2DR0 |
| XRCGB26M000F1S2FR0 | XRCGB37M400F1S1AR0 | XRCGB40M000F1S2ER0 |
| XRCGB26M000F1S2FR0 | XRCGB37M400F1S1BR0 | XRCGB40M000F1S2FR0 |
| XRCGB26M000F1S2FR0 | XRCGB37M400F1S1CR0 | XRCGB40M000F1S2GR0 |
| XRCGB26M000F1S2FR0 | XRCGB37M400F1S1DR0 | XRCGB40M000F1S2HR0 |
| XRCGB26M000F1S2KR0 | XRCGB37M400F1S1JR0 | XRCGB40M000F1S2JR0 |
| XRCGB26M000F1S2KR0 | XRCGB37M400F1S1LR0 | XRCGB40M000F1S2KR0 |

XRCGB26M000F1S2KR0
XRCGB26M000F1S2KR0
XRCGB26M000F1S2TR0
XRCGB26M000F1SAAR0
XRCGB26M000F1SABR0
XRCGB26M000F1SACR0

XRCGB37M400F1S2FR0
XRCGB37M400F1S2GR0
XRCGB37M400F1S2HR0
XRCGB37M400F1S2JR0
XRCGB37M400F1S2KR0
XRCGB37M400F1S2LR0

XRCGB40M000F1S2NR0
XRCGB40M000F1S2NR0
XRCGB40M000F1S2RR0
XRCGB40M000F1S2SR0
XRCGB40M000F1S2SR0
XRCGB40M000F1S2SR0