

Product Discontinuation Notice

January 2013

Discontinuation of F4S (18, 38 & 46 pin) Narrow Pitch Connector

Narrow-pitch connector
F4S

Mated height: 1.0 mm
18, 38 and 46 pin
contacts



1. Reason: Low market demand

2. Affected parts:

AXT518124 (Socket)
AXT618124 (Header)
AXT538124 (Socket)
AXT638124 (Header)
AXT546124 (Socket)
AXT646124 (Header)

3. Last time buy: End of September 2013

4. Substitution: Contact your local Panasonic sales representative

Any questions, please contact your local Panasonic Sales representatives.

(Ref#: T-1289-10)