

CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20180523
Issue Date 2020-JULY-14

Issued to: TRACO ELECTRONIC AG
Sihlbruggstrasse 111, CH-6340 Baar, SWITZERLAND.

**This certificate confirms that
representative samples of**

POWER SUPPLIES, INFORMATION TECHNOLOGY
EQUIPMENT INCLUDING ELECTRICAL BUSINESS
EQUIPMENT - COMPONENT;
POWER SUPPLIES FOR USE WITH AUDIO/VIDEO,
INFORMATION AND COMMUNICATION TECHNOLOGY
EQUIPMENT - COMPONENT
See Addendum Page


Have been investigated by UL in accordance with the
component requirements in the Standard(s) indicated on
this Certificate. UL Recognized components are incomplete
in certain constructional features or restricted in
performance capabilities and are intended for installation in
complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: See Addendum Page
Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20180523
Issue Date 2020-JULY-14

Standard(s) for Safety:

UL 62368-1 & CSA C22.2 No. 62368-1, CAN/CSA C22.2 No. 62368-1-14 Audio/video, Information and Communication Technology Equipment - Part 1: Safety Requirements

UL 60950-1 & CSA C22.2 No. 60950-1, Information Technology Equipment - Safety - Part 1: General Requirements



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20180523
Issue Date 2020-JULY-14

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

TMPS 10-103, TMPS 10-105, TMPS 10-109, TMPS 10-112, TMPS 10-115, TMPS 10-124, TMPS 10-148, TEL 10-2410WI, TEL 10-2411AWI, TEL 10-2411WI, TEL 10-2412WI, TEL 10-2413WI, TEL 10-2415WI, TEL 10-2422WI, TEL 10-2423WI, TEL 10-4810WI, TEL 10-4811AWI, TEL 10-4811WI, TEL 10-4812WI, TEL 10-4813WI, TEL 10-4815WI, TEL 10-4822WI, TEL 10-4823WI.

QQJQ2 & QQJQ8 Only


TMDC 06-2411B, TMDC 06-2411, TMDC 06-2412, TMDC 06-2413, TMDC 06-2415, TMDC 06-2418, TMDC 06-2422, TMDC 06-2423, TMDC 06-2425, TMDC 06-4811B, TMDC 06-4811, TMDC 06-4812, TMDC 06-4813, TMDC 06-4815, TMDC 06-4818, TMDC 06-4822, TMDC 06-4823, TMDC 06-4825, TMDC 10-2411B, TMDC 10-2411, TMDC 10-2412, TMDC 10-2413, TMDC 10-2415, TMDC 10-2418, TMDC 10-2422, TMDC 10-2423, TMDC 10-2425, TMDC 10-4811B, TMDC 10-4811, TMDC 10-4812, TMDC 10-4813, TMDC 10-4815, TMDC 10-4818, TMDC 10-4822, TMDC 10-4823, TMDC 10-4825, TMDC 06-7211H-B1, TMDC 06-7211H, TMDC 06-7212H, TMDC 06-7213H, TMDC 06-7215H, TMDC 06-7218H, TMDC 06-7222H, TMDC 06-7223H, TMDC 06-7225H, TMDC 10-7211H-B1, TMDC 10-7211H, TMDC 10-7212H, TMDC 10-7213H, TMDC 10-7215H, TMDC 10-7218H, TMDC 10-7222H, TMDC 10-7223H, TMDC 10-7225H, TRI 10-1210, TRI 10-1211-B1, TRI 10-1211, TRI 10-1212, TRI 10-1213, TRI 10-1215, TRI 10-1222, TRI 10-1223, TRI 10-2410, TRI 10-2411-B1, TRI 10-2411, TRI 10-2412, TRI 10-2413, TRI 10-2415, TRI 10-2422, TRI 10-2423, TRI 10-4810, TRI 10-4811-B1, TRI 10-4811, TRI 10-4812, TRI 10-4813, TRI 10-4815, TRI 10-4822, TRI 10-4823, TRI 3-0515, TRI 3-1215, TRI 3-2415, TRI 3-4815, TRI 6-1215, TRI 6-2415, TRI 6-4815

QQJQ2, QQJQ8 Only:

TEL 10-1210, TEL 10-1211-B1, TEL 10-1211, TEL 10-1212, TEL 10-1213, TEL 10-1215, TEL 10-1222, TEL 10-1223, , TEL 10-2410, TEL 10-2411-B1, TEL 10-2411, TEL 10-2412, TEL 10-2413, TEL 10-2415, TEL 10-2422, TEL 10-2423, , TEL 10-4810, TEL 10-4811-B1, TEL 10-4811, TEL 10-4812, TEL 10-4813, TEL 10-4815, TEL 10-4822, TMDC 20-7211H-B1, TMDC 20-7211H, TMDC 20-7212H, TMDC 20-7213H, TMDC 20-7215H, TMDC 20-7218H, TMDC 20-7222H, TMDC 20-7223H, TMDC 20-7225H, TMDC 40-7211H-B1, TMDC 40-7211H, TMDC 40-7212H, TMDC 40-7213H, TMDC 40-7215H, TMDC 40-7218H, TMDC 40-7222H, TMDC 40-7223H, TMDC 40-7225H.

QQJQ2 Only:

TEL 10-4823.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE


Certificate Number E188913
Report Reference E188913-20180523
Issue Date 2020-JULY-14

QQJQ2, QQJQ8 Only:

TMDC 60-7211H-B1, TMDC 60-7211H, TMDC 60-7212H, TMDC 60-7213H, TMDC 60-7215H, TMDC 60-7218H, TMDC 60-7222H, TMDC 60-7223H, TMDC 60-7225H, THR 3-2411WI, THR 3-2412WI, THR 3-2413WI, THR 3-2422WI, THR 3-2423WI, THR 3-4811WI, THR 3-4812WI, THR 3-4813WI, THR 3-4822WI, THR 3-4823WI, THR 3-7211WI, THR 3-7212WI, THR 3-7213WI, THR 3-7222WI, THR 3-7223WI.

TEL 12-1211, TEL 12-1212, TEL 12-1213, TEL 12-1215, TEL 12-1222, TEL 12-1223, TEL 12-2411, TEL 12-2412, TEL 12-2413, TEL 12-2415, TEL 12-2422, TEL 12-2423, TEL 12-4811, TEL 12-4812, TEL 12-4813, TEL 12-4815, TEL 12-4822, TEL 12-4823, TEL 12-2411WI, TEL 12-2412WI, TEL 12-2413WI, TEL 12-2415WI, TEL 12-2422WI, TEL 12-2423WI, TEL 12-4811WI, TEL 12-4812WI, TEL 12-4813WI, TEL 12-4815WI, TEL 12-4822WI, TEL 12-4823WI

TEN 40-1210N , TEN 40-1211N, TEN 40-1212N, TEN 40-1213N, TEN 40-1215N, TEN 40-1222N, TEN 40-1223N, TEN 40-2410N , TEN 40-2411N, TEN 40-2412N, TEN 40-2413N, TEN 40-2415N, TEN 40-2422N, TEN 40-2423N, TEN 40-4810N , TEN 40-4811N, TEN 40-4812N, TEN 40-4813N, TEN 40-4815N, TEN 40-4822N, TEN 40-4823N, TEN 40-1210N-HS, TEN 40-1211N-HS, TEN 40-1212N-HS, TEN 40-1213N-HS, TEN 40-1215N-HS, TEN 40-1222N-HS, TEN 40-1223N-HS, TEN 40-2410N -HS, TEN 40-2411N-HS, TEN 40-2412N-HS, TEN 40-2413N-HS, TEN 40-2415N-HS, TEN 40-2422N-HS, TEN 40-2423N-HS, TEN 40-4810N-HS, TEN 40-4811N-HS, TEN 40-4812N-HS, TEN 40-4813N-HS, TEN 40-4815N-HS, TEN 40-4822N-HS, TEN 40-4823N-HS, THL 10-1210, THL 10-1211, THL 10-1212, THL 10-1213, THL 10-1221 , THL 10-1222 , THL 10-1223, THL 10-2410, THL 10-2411, THL 10-2412, THL 10-2413, THL 10-2421 , THL 10-2422 , THL 10-2423, THL 10-4810, THL 10-4811, THL 10-4812, THL 10-4813, THL 10-4821 , THL 10-4822 , THL 10-4823, THL 10-1210-HS, THL 10-1211-HS, THL 10-1212-HS, THL 10-1213-HS, THL 10-1221-HS, THL 10-1222-HS, THL 10-1223-HS, THL 10-2410-HS, THL 10-2411-HS, THL 10-2412-HS, THL 10-2413-HS, THL 10-2421-HS, THL 10-2422-HS , THL 10-2423-HS, THL 10-4810-HS, THL 10-4811-HS, THL 10-4812-HS, THL 10-4813-HS, THL 10-4821-HS , THL 10-4822-HS , THL 10-4823-HS, THL 10-1210-RC, THL 10-1211-RC, THL 10-1212-RC, THL 10-1213-RC, THL 10-1221-RC, THL 10-1222-RC, THL 10-1223-RC, THL 10-2410-RC, THL 10-2411-RC, THL 10-2412-RC, THL 10-2413-RC, THL 10-2421-RC, THL 10-2422-RC , THL 10-2423-RC, THL 10-4810-RC, THL 10-4811-RC, THL 10-4812-RC, THL 10-4813-RC, THL 10-4821-RC , THL 10-4822-RC , THL 10-4823-RC, THL 10-1210-RCHS, THL 10-1211-RCHS, THL 10-1212-RCHS, THL 10-1213-RCHS, THL 10-1221-RCHS, THL 10-1222-RCHS, THL 10-1223-RCHS, THL 10-2410-RCHS, THL 10-2411-RCHS, THL 10-2412-RCHS, THL 10-2413-RCHS, THL 10-2421-RCHS, THL 10-2422-RCHS , THL 10-2423-RCHS, THL 10-4810-RCHS, THL 10-4811-RCHS, THL 10-4812-RCHS, THL 10-4813-RCHS, THL 10-4821-RCHS , THL 10-4822-RCHS , THL 10-4823-RCHS, THD 10-1210N, THD 10-1211N, THD 10-1212N, THD 10-1213N, THD 10-1222N, THD 10-1223N, THD 10-2410N, THD 10-2411N, THD 10-2412N, THD 10-2413N, THD 10-2422N, THD 10-2423N, THD 10-4810N, THD 10-4811N, THD 10-4812N, THD 10-4813N, THD 10-4822N, THD 10-4823N, TMDC 20-2411, TMDC 20-2412, TMDC 20-2415, TMDC 20-2418, TMDC 20-4811, TMDC 20-4812, TMDC 20-4815, TMDC 20-4818, TMDC 40-2411, TMDC 40-2412, TMDC 40-2415, TMDC 40-2418, TMDC 40-4811, TMDC 40-4812, TMDC 40-4815, TMDC 40-4818



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number E188913
Report Reference E188913-20180523
Issue Date 2020-JULY-14

QQJQ2, QQJQ8 Only:

TMDC 60-2411, TMDC 60-2412, TMDC 60-2415, TMDC 60-2418, TMDC 60-4811, TMDC 60-4812, TMDC 60-4815, TMDC 60-4818, TEN 50-2410, TEN 50-2411, TEN 50-2412, TEN 50-2413, TEN 50-2415, TEN 50-4810, TEN 50-4811, TEN 50-4812, TEN 50-4813, TEN 50-4815, TEN 50-2410-HS, TEN 50-2411-HS, TEN 50-2412-HS, TEN 50-2413-HS, TEN 50-2415-HS, TEN 50-4810-HS, TEN 50-4811-HS, TEN 50-4812-HS, TEN 50-4813-HS, TEN 50-4815-HS, TEN 40-2410WIN, TEN 40-2411WIN, TEN 40-2412WIN, TEN 40-2413WIN, TEN 40-2415WIN, TEN 40-2422WIN, TEN 40-2423WIN, TEN 40-4810WIN, TEN 40-4811WIN, TEN 40-4812WIN, TEN 40-4813WIN, TEN 40-4815WIN, TEN 40-4822WIN, TEN 40-4823WIN, TEN 40-2410WIN-HS, TEN 40-2411WIN-HS, TEN 40-2412WIN-HS, TEN 40-2413WIN-HS, TEN 40-2415WIN-HS, TEN 40-2422WIN-HS, TEN 40-2423WIN-HS, TEN 40-4810WIN-HS, TEN 40-4811WIN-HS, TEN 40-4812WIN-HS, TEN 40-4813WIN-HS, TEN 40-4815WIN-HS, TEN 40-4822WIN-HS, TEN 40-4823WIN-HS, TEM 3-0511N, TEM 3-0512N, TEM 3-0513N, TEM 3-0522N, TEM 3-0523N, TEM 3-1211N, TEM 3-1212N, TEM 3-1213N, TEM 3-1222N, TEM 3-1223N, TEM 3-2411N, TEM 3-2412N, TEM 3-2413N, TEM 3-2422N, TEM 3-2423N, THL 25-1210, THL 25-1211, THL 25-1212, THL 25-1213, THL 25-1222, THL 25-1223, THL 25-2410, THL 25-2411, THL 25-2412, THL 25-2413, THL 25-2422, THL 25-2423, THL 25-4810, THL 25-4811, THL 25-4812, THL 25-4813, THL 25-4822, THL 25-4823, THL 25-1210-HS, THL 25-1211-HS, THL 25-1212-HS, THL 25-1213-HS, THL 25-1222-HS, THL 25-1223-HS, THL 25-2410-HS, THL 25-2411-HS, THL 25-2412-HS, THL 25-2413-HS, THL 25-2422-HS, THL 25-2423-HS, THL 25-4810-HS, THL 25-4811-HS, THL 25-4812-HS, THL 25-4813-HS, THL 25-4822-HS, THL 25-4823-HS, TEN 50-2410WI, TEN 50-2411WI, TEN 50-2412WI, TEN 50-2413WI, TEN 50-2415WI, TEN 50-4810WI, TEN 50-4811WI, TEN 50-4812WI, TEN 50-4813WI, TEN 50-4815WI, TEN 50-2410WI-HS, TEN 50-2411WI-HS, TEN 50-2412WI-HS, TEN 50-2413WI-HS, TEN 50-2415WI-HS, TEN 50-4810WI-HS, TEN 50-4811WI-HS, TEN 50-4812WI-HS, TEN 50-4813WI-HS, TEN 50-4815WI-HS, TES 2-0511M, TES 2-0512M, TES 2-0513M, TES 2-0522M, TES 2-0523M, TES 2-1211M, TES 2-1212M, TES 2-1213M, TES 2-1222M, TES 2-1223M, TES 2-2411M, TES 2-2412M, TES 2-2413M, TES 2-2422M, TES 2-2423M, THI 3-0511, THI 3-0512, THI 3-0513, THI 3-0522, THI 3-0523, THI 3-1211, THI 3-1212, THI 3-1213, THI 3-1222, THI 3-1223, THI 3-2411, THI 3-2412, THI 3-2413, THI 3-2422, THI 3-2423, TEN 6-1210N, TEN 6-1211N, TEN 6-1212N, TEN 6-1213N, TEN 6-1215N, TEN 6-1221N, TEN 6-1222N, TEN 6-1223N, TEN 6-2410N, TEN 6-2411N, TEN 6-2412N, TEN 6-2413N, TEN 6-2415N, TEN 6-2421N, TEN 6-2422N, TEN 6-2423N, TEN 6-4810N, TEN 6-4811N, TEN 6-4812N, TEN 6-4813N, TEN 6-4815N, TEN 6-4821N, TEN 6-4822N, TEN 6-4823N, TEN 6-1210N-HI, TEN 6-1211N-HI, TEN 6-1212N-HI, TEN 6-1213N-HI, TEN 6-1215N-HI, TEN 6-1221N-HI, TEN 6-1222N-HI, TEN 6-1223N-HI, TEN 6-2410N-HI, TEN 6-2411N-HI, TEN 6-2412N-HI, TEN 6-2413N-HI, TEN 6-2415N-HI, TEN 6-2421N-HI, TEN 6-2422N-HI, TEN 6-2423N-HI, TEN 6-4810N-HI, TEN 6-4811N-HI, TEN 6-4812N-HI, TEN 6-4813N-HI, TEN 6-4815N-HI, TEN 6-4821N-HI, TEN 6-4822N-HI, TEN 6-4823N-HI, TEN 6-2410WIN, TEN 6-2411WIN, TEN 6-2412WIN, TEN 6-2413WIN, TEN 6-2415WIN, TEN 6-2421WIN, TEN 6-2422WIN, TEN 6-2423WIN, TEN 6-4810WIN, TEN 6-4811WIN, TEN 6-4812WIN, TEN 6-4813WIN, TEN 6-4815WIN, TEN 6-4821WIN, TEN 6-4822WIN, TEN 6-4823WIN, TEN 6-2410WIN-HI, TEN 6-2411WIN-HI, TEN 6-2412WIN-HI, TEN 6-2413WIN-HI



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE


Certificate Number E188913
Report Reference E188913-20180523
Issue Date 2020-JULY-14

QQJQ2, QQJQ8 Only:

TEN 6-2415WIN-HI, TEN 6-2421WIN-HI, TEN 6-2422WIN-HI, TEN 6-2423WIN-HI, TEN 6-4810WIN-HI, TEN 6-4811WIN-HI, TEN 6-4812WIN-HI, TEN 6-4813WIN-HI, TEN 6-4815WIN-HI, TEN 6-4821WIN-HI, TEN 6-4822WIN-HI, TEN 6-4823WIN-HI

QQJQ2, QQJQ8 Only:

TEL 8-1210, TEL 8-1211, TEL 8-1212, TEL 8-1213, TEL 8-1215, TEL 8-1222, TEL 8-1223, TEL 8-2410, TEL 8-2411, TEL 8-2412, TEL 8-2413, TEL 8-2415, TEL 8-2422, TEL 8-2423, TEL 8-4810, TEL 8-4811, TEL 8-4812, TEL 8-4813, TEL 8-4815, TEL 8-4822, TEL 8-4823, THL 25-2410WI, THL 25-2411WI, THL 25-2412WI, THL 25-2413WI, THL 25-2422WI, THL 25-2423WI, THL 25-4810WI, THL 25-4811WI, THL 25-4812WI, THL 25-4813WI, THL 25-4822WI, THL 25-4823WI, THL 25-2410WI-HS, THL 25-2411WI-HS, THL 25-2412WI-HS, THL 25-2413WI-HS, THL 25-2422WI-HS, THL 25-2423WI-HS, THL 25-4810WI-HS, THL 25-4811WI-HS, THL 25-4812WI-HS, THL 25-4813WI-HS, THL 25-4822WI-HS, THL 25-4823WI-HS, THD 10-2410WIN, THD 10-2411WIN, THD 10-2412WIN, THD 10-2413WIN, THD 10-2415WIN, THD 10-2422WIN, THD 10-2423WIN, THD 10-4810WIN, THD 10-4811WIN, THD 10-4812WIN, THD 10-4813WIN, THD 10-4815WIN, THD 10-4822WIN, THD 10-4823WIN, TEN 3-1210N, TEN 3-1211N, TEN 3-1212N, TEN 3-1213N, TEN 3-1215N, TEN 3-1221N, TEN 3-1222N, TEN 3-1223N, TEN 3-2410N, TEN 3-2411N, TEN 3-2412N, TEN 3-2413N, TEN 3-2415N, TEN 3-2421N, TEN 3-2422N, TEN 3-2423N, TEN 3-4810N, TEN 3-4811N, TEN 3-4812N, TEN 3-4813N, TEN 3-4815N, TEN 3-4821N, TEN 3-4822N, TEN 3-4823N, TEN 3-2410WIN, TEN 3-2411WIN, TEN 3-2412WIN, TEN 3-2413WIN, TEN 3-2415WIN, TEN 3-2421WIN, TEN 3-2422WIN, TEN 3-2423WIN, TEN 3-4810WIN, TEN 3-4811WIN, TEN 3-4812WIN, TEN 3-4813WIN, TEN 3-4815WIN, TEN 3-4821WIN, TEN 3-4822WIN, TEN 3-4823WIN



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

