



# Product Change Notification

## TE Connectivity

Product Change Notification: P-18-016122

PCN Date: 23-JUL-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
High Power Wire Wound Resistor Type TE series

**Description of Changes**  
The option of the resistor without the fixing bracket will no longer be offered. Please use the version with the bracket instead. 1879931-1 use 1879455-5

**Reason for Changes:**  
Product improvement. Due to customers purchasing the resistor without the bracket, then trying to purchase the fixing bracket, the product without the fixing bracket will no longer be offered as an option. This product is too large and heavy to be mounted without the fixing bracket.

Estimated Dates:	
<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
31-OCT-2018	
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
31-OCT-2018	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1879931-1</a>	YES		TE1500A2R2J			