

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU Type				
02	007	003	0000002361	See list below	Appliance inlet	1621

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
6163.0001	6163.0002	6163.0003	6163.0004	6163.0005	6163.0006	6163.0007	6163.0008
6163.0009	6163.0025	6163.0030					


2 Type of change

Modification of approval marks.


3 Detailed description of change

New combined cURus approval mark instead of separate UR and CSA marks.

Old marking



New marking



4 Reason of change

Consolidation of North American approval marks with the combined cURus mark.

5 Released date

The change will be rolled-out individually by all part numbers affected starting ww 50/2015 and last approx. 9 months.

6 Impact of change and recommended action

Form	No	No change in the form
Fit	No	There are no dimensional changes
Function	No	No change in the specification
Production Site	No	There is no change of the production site
Product Label	Yes	CSA and UR marks replaced by cURus mark.
Customer Action	No	No customer action required

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data Sheet 1621		

1621 Appliance Inlet					0118.2308	
creation date	created by	release date	released by	notification no.	revision	page
2015-09-11	hotzar	2015-10-22	hotzar	27860	-	1 of 1