

TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc.
10 N. Martingale Rd.
Schaumburg, IL 60173
Tel (630) 237-2405 Fax (847) 240-1715
<http://www.t-yuden.com>

Notice of Discontinuation for Taiyo Yuden (U.S.A.) Inc. Distributors

DATE: July 8th, 2016
RE: Discontinuation of Axial Leaded Ceramic Capacitors
REF NO.: UTY-DN16-07D

In addition, while not released through Taiyo Yuden distribution sales' channels, the following part series are to be discontinued effective immediately. As there is no sales history for these parts, no last time buy orders will be accepted.

Discontinued Part Series
EP025B103M_Series
EP025B122M_Series
EP025B123M_Series
EP025B152M_Series
EP025B153M_Series
EP025B182M_Series
EP025B183M_Series
EP025B222M_Series
EP025B223M_Series
EP025B272M_Series
EP025B332M_Series
EP025B392M_Series
EP025B472M_Series
EP025B562M_Series
EP025B682M_Series
EP025B822M_Series
EP025F105Z_Series
EP025F224Z_Series
EP025F474Z_Series
EP050F225Z_Series
GP075B5106K_Series
GP075F106Z_Series
LP050F106Z_Series
LP050F475Z_Series
TP025F103Z_Series
TP025F223Z_Series
TP025F473Z_Series
UP025B122K_Series

Discontinued Part Series
UP025B153K_Series
UP025SL010D_Series
UP025SL100J_Series
UP025SL120J_Series
UP025SL150J_Series
UP025SL180J_Series
UP025SL1R2D_Series
UP025SL1R5D_Series
UP025SL1R8D_Series
UP025SL220J_Series
UP025SL270J_Series
UP025SL2R2D_Series
UP025SL2R7D_Series
UP025SL330J_Series
UP025SL390J_Series
UP025SL3R3D_Series
UP025SL3R9D_Series
UP025SL470J_Series
UP025SL4R7D_Series
UP025SL560J_Series
UP025SL5R6K_Series
UP025SL680J_Series
UP025SL6R8K_Series
UP025SL820J_Series
UP025SL8R2K_Series
UP050CH750J_Series
UP075B5475K_Series

NOTE: The information in this notice is applicable only to Taiyo Yuden (U.S.A.) Inc distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department