

# PRODUCT CHANGE NOTIFICATION

**PCN#:** CABLE COPPER, FIBER CABLE AND CONNECTORS **20190218-001**

**ISSUE DATE:** February 18,2019

**IMPACTED REGIONS:**  NA  EMEA  LATAM  AP

**REASON FOR CHANGE:**  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Not Required for discontinuation)**

Parts in Column A have been replaced by parts in Column B due to CPR Initiative in EMEA region. Column A parts have not had sales or inventory in more than 6 months. Please code OBS.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

| SCHEDULE FOR CHANGE                  | Year<br>(YYYY) | Month<br>(MM) | Day<br>(DD) |
|--------------------------------------|----------------|---------------|-------------|
| New product sample availability date | 2018           | 2             | 18          |
| Old product discontinuation date*    | 2019           | 2             | 18          |

**\*Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

| IMPACTED PART NUMBER(s) | REPLACEMENT PART NUMBER(s) |
|-------------------------|----------------------------|
| FPCL504                 | FACC504-24                 |
| FPCL508                 | FACC508-24                 |
| FPCL512                 | FACC512-24                 |
| FPCL524                 | FACC524-24                 |
| FPCL604                 | FACC604-24                 |
| FPCL608                 | FACC608-24                 |
| FPCL612                 | FACC612-24                 |
| FPCL624                 | FACC624-24                 |
| FPCL904                 | FACC904-24                 |
| FPCL908                 | FACC908-24                 |
| FPCL912                 | FACC912-24                 |
| FPCL924                 | FACC924-24                 |
| FQCLX04                 | FACCX04-24                 |
| FQCLX08                 | FACCX08-24                 |
| FQCLX12                 | FACCX12-24                 |
| FQCLX16                 | FACCX16-24                 |
| FQCLX24                 | FACCX24-24                 |
| FQCLZ04                 | FACCZ04-24                 |
| FQCLZ08                 | FACCZ08-24                 |
| FQCLZ12                 | FACCZ12-24                 |
| FQCLZ16                 | FACCZ24-24                 |
| FPDL504                 | FADC504-24                 |
| FPDL604                 | FADC604-24                 |
| FPDL906                 | FADC906-24                 |
| FPDL506                 | FADC506-24                 |
| FPDL606                 | FADC606-24                 |
| FPDL508                 | FADC508-24                 |
| FPDL608                 | FADC608-24                 |
| FPDL512                 | FADC512-24                 |
| FPDL612                 | FADC612-24                 |
| FPDL916                 | FADC916-24                 |
| FPDL516                 | FADC516-24                 |
| FPDL616                 | FADC616-24                 |
| FPDL524                 | FADC524-24                 |
| FPDL624                 | FADC624-24                 |
| FPDL936                 | FAEC936-24                 |
| FPDL536                 | FAEC536-24                 |
| FPDL636                 | FAEC636-24                 |
| FPDL948                 | FAEC948-24                 |
| FPDL548                 | FAEC548-24                 |
| FPDL648                 | FAEC648-24                 |
| FPDL972                 | FAEC972-24                 |
| FPDL572                 | FAEC572-24                 |
| FPDL672                 | FAEC672-24                 |
| FPDL996                 | FAEC996-24                 |
| FPDL596                 | FAEC596-24                 |

|         |            |
|---------|------------|
| FPDL696 | FAEC696-24 |
| FQDLZ04 | FADCZ04-24 |
| FQDLX06 | FADCX06-24 |
| FQDLZ06 | FADCZ06-24 |
| FQDLZ08 | FADCZ08-24 |
| FQDLZ12 | FADCZ12-24 |
| FQDLX16 | FADCX16-24 |
| FQDLZ16 | FADCZ16-24 |
| FQDLZ24 | FADCZ24-24 |
| FQDLX36 | FAECX36-24 |
| FQDLZ36 | FAECZ36-24 |
| FQDLX48 | FAECX48-24 |
| FQDLZ48 | FAECZ48-24 |
| FQDLX72 | FAECX72-24 |
| FQDLZ72 | FAECZ72-24 |
| FQDLX96 | FAECX96-24 |
| FQDLZ96 | FAECZ96-24 |
| FPDL904 | FADC904-24 |
| FPDL908 | FADC908-24 |
| FPDL912 | FADC912-24 |
| FPKL502 | FAKC502-14 |
| FPKL504 | FAKC504-14 |
| FPKL506 | FAKC506-14 |
| FPKL508 | FAKC508-14 |
| FPKL512 | FAKC512-14 |
| FPKL524 | FAKC524-14 |
| FPKL536 | FAKC536-14 |
| FPKL548 | FAKC548-14 |
| FPKL572 | FAKC572-14 |
| FPKL596 | FAKC596-14 |
| FPKL602 | FAKC602-14 |
| FPKL604 | FAKC604-14 |
| FPKL606 | FAKC606-14 |
| FPKL608 | FAKC608-14 |
| FPKL612 | FAKC612-14 |
| FPKL624 | FAKC624-14 |
| FPKL636 | FAKC636-14 |
| FPKL648 | FAKC648-14 |
| FPKL672 | FAKC672-14 |
| FPKL696 | FAKC696-14 |
| FPKL902 | FAKC902-14 |
| FPKL904 | FAKC904-14 |
| FPKL906 | FAKC906-14 |
| FPKL908 | FAKC908-14 |
| FPKL912 | FAKC912-14 |
| FPKL924 | FAKC924-14 |
| FPKL936 | FAKC936-14 |

|         |            |
|---------|------------|
| FPKL948 | FAKC948-14 |
| FPKL972 | FAKC972-14 |
| FPKL996 | FAKC996-14 |
| FQKLX02 | FAKCX02-14 |
| FQKLX04 | FAKCX04-14 |
| FQKLX06 | FAKCX06-14 |
| FQKLX08 | FAKCX08-14 |
| FQKLX12 | FAKCX12-14 |
| FQKLX24 | FAKCX24-14 |
| FQKLX36 | FAKCX36-14 |
| FQKLX48 | FAKCX48-14 |
| FQKLX72 | FAKCX72-14 |
| FQKLX96 | FAKCX96-14 |
| FQKLZ02 | FAKCZ02-14 |
| FQKLZ04 | FAKCZ04-14 |
| FQKLZ06 | FAKCZ06-14 |
| FQKLZ08 | FAKCZ08-14 |
| FQKLZ12 | FAKCZ12-14 |
| FQKLZ24 | FAKCZ24-14 |
| FQKLZ36 | FAKCZ36-14 |
| FQKLZ48 | FAKCZ48-14 |
| FQKLZ72 | FAKCZ72-14 |
| FQKLZ96 | FAKCZ96-14 |
| FPNL936 | FANC936-40 |
| FPNL536 | FANC536-40 |
| FPNL636 | FANC636-40 |
| FQNLX36 | FANCX36-40 |
| FQNLZ36 | FANCZ36-40 |
| FPNL948 | FANC948-40 |
| FPNL548 | FANC548-40 |
| FPNL648 | FANC648-40 |
| FQNLX48 | FANCX48-40 |
| FQNLZ48 | FANCZ48-40 |
| FPNL972 | FANC972-40 |
| FPNL572 | FANC572-40 |
| FPNL672 | FANC672-40 |
| FQNLX72 | FANCX72-40 |
| FQNLZ72 | FANCZ72-40 |
| FPNL996 | FANC996-40 |
| FPNL596 | FANC596-40 |
| FPNL696 | FANC696-40 |
| FQNLX96 | FANCX96-40 |
| FQNLZ96 | FANCZ96-40 |
| FPNL91A | FANC91A-40 |
| FPNL51A | FANC51A-40 |
| FPNL61A | FANC61A-40 |
| FQNLX1A | FANCX1A-40 |

|            |                    |
|------------|--------------------|
| FQNLZ1A    | FANCZ1A-40         |
| FADC504-14 | NA-Set up in error |
| FADC604-14 | NA-Set up in error |
| FADC906-14 | NA-Set up in error |
| FADC506-14 | NA-Set up in error |
| FADC606-14 | NA-Set up in error |
| FADC508-14 | NA-Set up in error |
| FADC608-14 | NA-Set up in error |
| FADC512-14 | NA-Set up in error |
| FADC612-14 | NA-Set up in error |
| FADC916-14 | NA-Set up in error |
| FADC516-14 | NA-Set up in error |
| FADC616-14 | NA-Set up in error |
| FADC524-14 | NA-Set up in error |
| FADC624-14 | NA-Set up in error |
| FADCZ04-14 | NA-Set up in error |
| FADCX06-14 | NA-Set up in error |
| FADCZ06-14 | NA-Set up in error |
| FADCZ08-14 | NA-Set up in error |
| FADCZ12-14 | NA-Set up in error |
| FADCX16-14 | NA-Set up in error |
| FADCZ16-14 | NA-Set up in error |
| FADCZ24-14 | NA-Set up in error |
| FADC912-14 | NA-Set up in error |
| FADCX08-14 | NA-Set up in error |
| FADCX12-14 | NA-Set up in error |
| FADCX24-14 | NA-Set up in error |
| FADC904-14 | NA-Set up in error |
| FADC908-14 | NA-Set up in error |
| FADC924-14 | NA-Set up in error |