

## Product Change Notice

PCN#: EE-PCN21017

09/17/2021

### CLASSIFICATION OF CHANGE:

End of Life

### DESCRIPTION OF CHANGE:

The A304 series of fuses have reached end of life. There are no drop-in replacements, but several alternative fuses exist. Please contact Tech Support [ELXTechSupport@Eaton.com](mailto:ELXTechSupport@Eaton.com), [Contact Us](#) or your local Eaton sales representative to find a suitable alternative for your application

### REASON FOR CHANGE:

Due to low sales volume and the availability of similar fuses, the product has reached end of life.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

N/A

### PARTS FAMILIES AFFECTED

Part Number
BK-A304-1-5A
BK-A304-10A
BK-A304-1A
BK-A304-250MA
BK-A304-2A
BK-A304-3A
BK-A304-500MA
BK-A304-5A
BK-A304-7A
BK1-A304-1-5A
BK1-A304-10A

Part Number
BK1-A304-1A
BK1-A304-2A
BK1-A304-3A
BK1-A304-500MA
BK1-A304-7A
BK1-A304-5A
BK1-A304-1-5-RE
BK1-A304-1-5A
BK1-A304-1-RE
BK1-A304-10-RE
BK1-A304-10A

Part Number
BK1-A304-1A
BK1-A304-2-RE
BK1-A304-250MA
BK1-A304-2A
BK1-A304-3-RE
BK1-A304-3A
BK1-A304-5-RE
BK1-A304-500MA
BK1-A304-5A
BK1-A304-7-RE
BK1-A304-7A

### TIME SCHEDULE:

Effective immediately

### ISSUED BY:

Jenan Krouchick  
Product Manager – Circuit Protection

### CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html>