



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

**Aug 31<sup>st</sup>, 2016**

**Product Inner Packing Pallet Change for LSP05, LSP05G and LSP10 Series (PCN# 4561E )**

Dear Valued Customers,

Littelfuse would like to notify you of a change relating to the product inner packing pallet for LSP05, LSP05G and LSP10 product series.

We will change the material of inner packing pallet from current polystyrene to a more environmentally friendly corrugated paperboard. The current minimum packing quantity, delivery quantity and the outer carton size will be remained with no changes.

Please refer the current and new inner packing pallet photo and the affected part number list below. This new inner packing pallet will be used from **September 30<sup>th</sup>, 2016**; during this transition period, customers are expected to receive the product with polystyrene inner pack pallet until current inventory in our warehouse and distribution channels are depleted.

Inner Packing Pallet Photo:



20160805 Product  
Inner Packing Photo.:

Affected Part Number Listing:



20160805 Product  
Inner Packing Pallet (

Please respond to us by **September 15<sup>th</sup>, 2016** to acknowledge notification of this change. If we do not hear from you then we will expect that this change has been accepted and no further action is required. Thank you.

Best Regards  
Johnny Chang  
Global Product Manager  
Littelfuse, Inc.  
[www.littelfuse.com](http://www.littelfuse.com)



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

## **LFPFN\_4561E Affected Parts List**

---

### **Materials**

---

LSP05120P  
LSP05120PM  
LSP05240LLP  
LSP05240LLPM  
LSP05240P  
LSP05240PM  
LSP05240PMX3316  
LSP05240PX3286  
LSP05240PX3316  
LSP05240PX3333  
LSP05277NP  
LSP05277NPX3324  
LSP05277P  
LSP05277PM  
LSP05277PMX3316  
LSP05277PX3316  
LSP05277PX3333  
LSP05277PX3333L250  
LSP05277PX3444  
LSP05277PX3507  
LSP05347P  
LSP05347PM  
LSP05480LLP  
LSP05480LLPM  
LSP05480P  
LSP05480PM  
LSP05480PX3382  
LSP05480PX3444  
LSP05G120P  
LSP05G120S  
LSP05G240P  
LSP05G240PHX3333  
LSP05G240PX3316  
LSP05G240PX3333  
LSP05G240S  
LSP05G240SHX3333  
LSP05G240SX3316  
LSP05G240SX3333  
LSP05G240SX3379  
LSP05G240SX3418  
LSP05G240SX3466  
LSP05G240SX3485  
LSP05G240SX3509  
LSP05G277P  
LSP05G277PX3316  
LSP05G277PX3333  
LSP05G277S



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

LSP05G277SX3316  
LSP05G277SX3333  
LSP05G277SX3370  
LSP05G277SX3418  
LSP05G277SX3485  
LSP05G277SX3500  
LSP05G347P  
LSP05G347S  
LSP05G480P  
LSP05G480S  
LSP10120P  
LSP10120PX3499  
LSP10120S  
LSP10240LLP  
LSP10240LLS  
LSP10240P  
LSP10240PX3316  
LSP10240PX3333  
LSP10240PX3412  
LSP10240PX3430  
LSP10240S  
LSP10240SX3316  
LSP10240SX3333  
LSP10240SX3388  
LSP10277P  
LSP10277PC  
LSP10277PMD  
LSP10277PMDX3421  
LSP10277PX3237  
LSP10277PX3284  
LSP10277PX3316  
LSP10277PX3333  
LSP10277PX3334  
LSP10277PX3373  
LSP10277PX3386  
LSP10277PX3447  
LSP10277S  
LSP10277SC  
LSP10277SX3257  
LSP10277SX3269  
LSP10277SX3284  
LSP10277SX3293  
LSP10277SX3298  
LSP10277SX3316  
LSP10277SX3333  
LSP10277SX3334  
LSP10277SX3420  
LSP10277SX3450  
LSP10277SX3464  
LSP10277SX3465



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631 [www.littelfuse.com](http://www.littelfuse.com)

LSP10277SX3472  
LSP10277SX3476  
LSP10347P  
LSP10347S  
LSP10480LLP  
LSP10480LLS  
LSP10480P  
LSP10480PX3334  
LSP10480PX3373  
LSP10480PX3386  
LSP10480PX3447  
LSP10480S  
LSP10480SX3257  
LSP10480SX3284  
LSP10480SX3334  
LSP10480SX3450