

Discontinuation of HL2-SFD-K

PDN.ACBD255.06.25.2014

06/25/2014

Effective Date:	Immediately
Last Time Buy Date:	June 30, 2013
Last Time Ship Date:	N/A
Discontinuation Details:	Panasonic is discontinuing the HL2-SFD-K due to a redundancy in product offering. The AHKA21 is a form, fit, and functional replacement.
Suggested Replacement:	HK2-DIN terminal socket (P/N :AHKA21)
Affected Part Numbers:	HL2-SFD-K
Datasheets:	N/A
Notes:	