



# Product Change Notification

## TE Connectivity

Product Change Notification: E-17-009032

PCN Date: 23-JUN-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:  
D-142-50/-51/-52 (CD)

Description of Changes  
This is only an administrative error of color. One melt-able ring should be grey and not clear. An error of typing. The drawing for the listed part number has been modified for clarification only.

Reason for Changes:  
Document Clarification. Update CD to completed accuracy  
Estimated Dates:  
Last Order Date (Obsolete Parts Only):                      First Date To Ship (Changed Parts Only):  
Last Ship Date (Obsolete Parts Only):                      Last Date for Mixed Shipments: (Changed Parts Only):  
No Mixed Shipments

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Note: This PCN contains only document changes, these changes do not affect the form, fit or function of the parts referenced.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
D-142-50/-51/-52	621054-000		2	

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
D-142-50/-51/-52	621054-000		2	