

Engineering Change Notice

Date: 2020/06/19 ECN No: 202006-4M01 ☑ Material / Specification Change Equipment change Change type □Process change Personnel change From next **Product** Affected date SPEAKER SP-1609S-1 of the change shipment name Reason of change: The original bracket used with 1609S-1 was discontinued, and has been replaced with the conventional bracket used in the same series of 1609S. This ECN will assist with procurement and subsequent supply-chain management. Content of Change Before change: After change: Diagram Diagram Tol: ±0.5 Unit: mm Impact of this change to customer: 1. Similar characteristics, no impact on function 2. Change the position of the spring terminal and the sticker; slight adjustment required. Please note acceptance by the customer.