



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001039

DATE: 26-Jul-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX3277U/D	N/A	26-Jul-2022	22-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX3654ETE+	N/A	26-Jul-2022	22-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX3654ETE+T	N/A	26-Jul-2022	22-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX844ISA+	N/A	26-Jul-2021	22-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX844ISA+T	N/A	25-Jan-2022	25-Jan-2022	Part can no longer be manufactured
Discontinuance	MAX86906EFD+	N/A	02-Aug-2022	29-Jan-2023	Part can no longer be manufactured
Discontinuance	MAX86906EFD+T	N/A	02-Aug-2022	29-Jan-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2021