

## Global Change Notification (GCN)

Product Family	HDMI cable	10636170
		GCN Number
Series	Individual of 68767	April 28, 2014
		Date Issued
Reason For Change	Change Construction Or Material	
Change Description	The purpose of this letter is to inform you that HDMI overmold 687670055/0048 will have below change: use black PVC resin 887800019 to replace PE 887800008 mixed with black master 172001037 This letter takes the place of notice customer the reason of change is supplier obsolete black master 172001037 used in these PNs, and we can use PVC resin 887800019 as replacement to reach some function We verify Impact of the change is confirmed as No change as current product.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Medical Industry	
Assessment Of Change (How Product Will Be Qualified & Validated)	887800019 passed Molex qualification test, and It's an existing resin used on HDMI 687670048 and 687670055	
Internal Molex Qualification Date (Planned Date Information Available)	September 26, 2002	
Sample Availability Date (Changed Part)	April 30, 2014	
Date of Implementation	April 30, 2014	
Method of Identifying Change	Date code	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

687670048

687670055