



Product Change Notice

Product Change Notification Number: PCN-RapID-NI-B

Title: Updating part numbers for RapID modules

Date of Notification: 03/10/2017

Effective Date: 5/1/17

Description of Change:

A dash (-) is being inserted in place of the current space () in the part number to conform to SAP requirements.

Innovasic Part Numbers Affected

Current Part number	New Part number
RapID-NI V2003	RapID-NI-V2003
RapID-NI V2005	RapID-NI-V2005
RapID-NI V2006	RapID-NI-V2006
RapID-NI V2007	RapID-NI-V2007
RapID-NI V2008	RapID-NI-V2008
RapID-NI V2009	RapID-NI-V2009
RapID-NI V2010	RapID-NI-V2010
RapID-NI V2011	RapID-NI-V2011
RapID-NI V2012	RapID-NI-V2012
RapID-NI V2105	RapID-NI-V2105
RapID-NI V2106	RapID-NI-V2106
RapID-NI V2107	RapID-NI-V2107
RapID-NI V2108	RapID-NI-V2108
RapID-NI V2109	RapID-NI-V2109
RapID-NI V2110	RapID-NI-V2110
RapID-NI V2111	RapID-NI-V2111
RapID-NI V2112	RapID-NI-V2112

Impact of Change to the Customer: Updated part numbers for orders after 5/1/17



PCN Revision History:

<u>Revision</u>	<u>Date</u>	<u>Reason for Change</u>
A	2/20/17	Components no longer offered
B	3/10/17	Replacing a space with a dash in the part number to conform to SAP requirements.

For More Information:

Tom Weingartner	505-883-5263 x-122	tweingartner@innovasic.com
------------------------	---------------------------	-----------------------------------

IMPORTANT NOTICE

CUSTOMER RESPONSE FOR ACCEPTANCE OR CONCERNS IS EXPECTED WITHIN 10 DAYS OF THE NOTICE. IN ORDER TO MINIMIZE RISKS ASSOCIATED WITH THE CUSTOMER'S APPLICATIONS, ADEQUATE DESIGN AND OPERATING SAFEGUARDS MUST BE PROVIDED BY THE CUSTOMER TO MINIMIZE INHERENT OR PROCEDURAL HAZARDS.

CERTAIN APPLICATIONS USING SEMICONDUCTOR PRODUCTS MAY INVOLVE POTENTIAL RISKS OF DEATH, PERSONAL INJURY OR ENVIRONMENTAL DAMAGE. INNOVASIC PRODUCTS ARE NOT DESIGNED, WARRANTED OR AUTHORIZED TO BE SUITABLE FOR USE IN LIFE-SUPPORT DEVICES, SYSTEMS OR OTHER CRITICAL APPLICATIONS. INCLUSION OF INNOVASIC PRODUCTS IN SUCH APPLICATIONS IS TO BE FULLY AT THE CUSTOMER'S RISK.