



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-128545

PCN Date: 17-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Heat Shrink Tubing Stick (-STK) products

Description of Changes
This PCN is to inform customers of changes to the packaging of the boxes used for the Heat Shrink Tubing products supplied in the Stick format (-STK, 1.2metre/4ft lengths). For more clarification check reference attachments

Reason for Changes:

PCN Attributes:

Product Category:	Kind of Change:
Heat Shrink Tubing	Packaging Type
Change Feature:	Potential Customer Impact:
Bulk	No Customer Impact

Remarks:
The new packaging is to improve the robustness of the packaging during transportation and storage. It moves away from the square cross section boxes to a more rectangular cross section. This gives greater stability when boxes are stacked and improves the strength of the boxes.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
04-FEB-2022	04-FEB-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
04-FEB-2022	04-FEB-2022
Effectivity Date:	Date of First Samples:
04-FEB-2022	04-FEB-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
363884-000	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CV37322001	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2290-000	NO			"DWFR-9/3-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2295-000	NO			"DWFR-4/1-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EH2300-000	NO			"DWFR-32/8-0-STK"			
EH2301-000	NO			"DWFR-52/13-0-STK"			
NB07072001	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2301-000	NO			"DWFR-52/13-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CV37322001	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2295-000	NO			"DWFR-4/1-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EH2300-000	NO			"DWFR-32/8-0-STK"			
EH2301-000	NO			"DWFR-52/13-0-STK"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
085193P003	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
193197P004	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
5233452001	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
636901P014	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
895231P008	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
9170152001	NO			"1-1197118-5", "DWP-125-2-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CV37322001	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
CZ0181-000	NO			"SCT-NO.5-Z4-0-STK"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-18-0-STK"			
E43149-000	NO			"3-1199653-6", "FL2500-NO.2-19-0-STK"			
EH2288-000	NO			"DWFR-3/1-0-STK"			
EH2292-000	NO			"DWFR-19/6-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2294-000	NO			"DWFR-40/13-0-STK"			
EH2295-000	NO			"DWFR-4/1-0-STK"			
EH2299-000	NO			"DWFR-24/6-0-STK"			
EH2300-000	NO			"DWFR-32/8-0-STK"			
EH2301-000	NO			"DWFR-52/13-0-STK"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07152001	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035377P004	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
063725P022	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
121397P024	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
130599P006	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
363884-000	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
537637P041	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
543633P064	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
576105P004	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
607381P046	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
829131P021	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
E95757-000	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
EH2289-000	NO			"DWFR-6/2-0-STK"			
EH2290-000	NO			"DWFR-9/3-0-STK"			
EH2291-000	NO			"DWFR-12/4-0-STK"			
EH2293-000	NO			"DWFR-24/8-0-STK"			
EH2297-000	NO			"DWFR-12/3-0-STK"			
EH2298-000	NO			"DWFR-16/4-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EH2299-000	NO			"DWFR-24/6-0-STK"			
NB07072001	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
NB07092001	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
NB07132001	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
NB07172001	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			