



1/24/2019

Subject: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type (Only Checked Changes Apply)		
<input type="checkbox"/> Production/assembly location	<input type="checkbox"/> Material	<input type="checkbox"/> End of Life w/ replacement
<input type="checkbox"/> Part Number/Ordering Code	<input type="checkbox"/> Packaging	<input type="checkbox"/> End of Life w/o replacement
<input type="checkbox"/> Country of Origin	<input type="checkbox"/> Point of Purchase	<input type="checkbox"/> Additional tool/refurbishment
<input type="checkbox"/> Design (fit, form, function)	<input type="checkbox"/> Point of Pick up	<input type="checkbox"/> Cost/Lead Time
<input type="checkbox"/> Engineering record (non-fit, form, function)	<input checked="" type="checkbox"/> Supply Chain	<input type="checkbox"/> Process
Additional Information		
From: Dupont MT409 AHS BK	To: Ascend 47H BK	
<p>As a risk mitigation for plastic resin supply, we are introducing an alternative supplier. This allows flexibility to maneuver dynamic market conditions. These resins are comparable, both fulfilling all product specifications.</p> <p>This change is effective February 1, 2019 and will be conducted as a running change. PPAP, or product data as according to print, will be provided upon request, as it becomes available.</p>		
Scope		
HT PN / Ordering Code	Customer PN	
157-00281	1436-1978-ND	
157-00284	1436-1981-ND	
157-00285	1436-1982-ND	
157-00283	1436-1980-ND	
157-00282	1439-1979-ND	
151-01975	151-01975-ND	
WMBH	WMBH-ND	
151-01652	151-01652-ND	
151-01637	1436-1692-ND	
151-01651	151-01651-ND	
151-01645	1436-1693-ND	
151-01499	1436-1691-ND	
151-02099	1436-1847-ND	
151-01661	1436-1695-ND	
151-01440	1436-1689-ND	
151-01653	1436-1694-ND	
151-01474	1436-1690-ND	
157-00034	1436-1419-ND	

151-01022	1436-1962-ND
157-00286	1436-1983-ND
157-00402	1436-1784-ND
HDM190HIRC2	1436-1823-ND
HDM3120HIRH4	HDM3120HIRH4-ND
132-00010	1436-1573-ND
HDM401HIHSUVH4	HDM401HIHSUVH4-ND
151-02098	1436-1845-ND
157-00400	1436-1760-ND
T255S0HIRX2	1436-1260-ND
151-02094	1436-1846-ND
T120RSM0HIRK2	1436-1010-ND
MSBT1200HIRHSH1	MSBT1200HIRHSH1-ND
HDM3120HIRC2	1436-1016-ND
132-00011	1436-1575-ND
151-00663	151-00663-ND
151-01224	1436-1848-ND
132-00009	1436-1303-ND
151-00629	151-00629-ND
111-12301	1436-1418-ND
DCT90HIRK2	1436-1305-ND
126-00049	1436-1040-ND
T255R0HIRX2	1436-1455-ND
DCT110HIRK2	1436-1306-ND
111-12302	1436-1420-ND
156-00069	156-00069-ND
156-00070	1436-1634-ND
156-00071	1436-1748-ND
CTT60R0HIRC2	CTT60R0HIRC2-ND
151-00927	1436-1317-ND
DCT90HIRC2	1436-1786-ND
156-00067	1436-1747-ND
156-00068	1436-1632-ND
156-00072	1436-1633-ND
156-00074	1436-1019-ND
156-00468	1436-1509-ND
156-00538	1436-1753-ND
156-00539	1436-1078-ND
156-00540	1436-1073-ND
156-00860	1436-1068-ND
156-00861	1436-1064-ND
156-00862	1436-1074-ND
156-00864	1436-1077-ND
156-00865	1436-1072-ND

*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 2/1/2019, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Todd Franz
Quality Project Administrator