



# Product Change Notification

## TE Connectivity

Product Change Notification: P-17-014333

PCN Date: 24-APR-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
AMPLIMITE Crimp Contacts and TE product using them

**Description of Changes**  
Increasing internal manufacturing capacity for AMPLIMITE, size 20 Crimp Pin and Socket Contacts. Specifically, TE PNs 205089-1 (AS39029/64-369), 205089-4 (NASA G-10-P1) and 205090-1 (AS39029/63-368).

**Reason for Changes:**  
TE Connectivity is adding additional internal capacity in other TE facilities in anticipation of increased demand. This product will continue to conform to AS39029 and NASA S-311-P-4/09 specifications. Agency notifications to NAVAIR and NASA are in process. Parts affected include AMPLIMITE Connector Kits and Assemblies, LGH Connectors, and PNP Cable Assemblies which use these contacts.

**Estimated Dates:**

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	24-JUL-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1757819-0</a>	NO			"CV0351-000", "AMP-1-1757819-0"			
<a href="#">1-1757820-0</a>	NO						
<a href="#">1757819-6</a>	NO			"CN5229-000", "AMP-0-1757819-6"			
<a href="#">1757819-7</a>	NO			"EH2240-000", "AMP-0-1757819-7"			
<a href="#">1757819-8</a>	NO						
<a href="#">1757819-9</a>	NO						
<a href="#">1757820-6</a>	NO			"CN5230-000", "AMP-0-1757820-6"			
<a href="#">1757820-7</a>	NO						
<a href="#">1757820-8</a>	NO			"CN5231-000", "AMP-0-1757820-8"			
<a href="#">1757820-9</a>	NO						
<a href="#">205089-1</a>	NO		A2160-ND	"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
<a href="#">205089-4</a>	NO						
<a href="#">205090-1</a>	NO		A2161-ND	"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			
<a href="#">205090-2</a>	NO						
<a href="#">205555-2</a>	NO			"EF5284-000", "AMP-0-0205555-2"			
<a href="#">205556-2</a>	NO						
<a href="#">205557-2</a>	NO						
<a href="#">205558-2</a>	NO						
<a href="#">205559-2</a>	NO						
<a href="#">205560-2</a>	NO						
<a href="#">205561-2</a>	NO						
<a href="#">205562-2</a>	NO						
<a href="#">205563-2</a>	NO						
<a href="#">205564-2</a>	NO						
<a href="#">862004-1</a>	NO						
<a href="#">866182-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1757819-0</a>	NO			CV0351-000, "AMP-1-1757819-0"			
<a href="#">1-1757820-0</a>	NO						
<a href="#">1757819-6</a>	NO			CN5229-000, "AMP-0-1757819-6"			
<a href="#">1757819-7</a>	NO			EH2240-000, "AMP-0-1757819-7"			
<a href="#">1757819-8</a>	NO						
<a href="#">1757819-9</a>	NO						
<a href="#">1757820-6</a>	NO			CN5230-000, "AMP-0-1757820-6"			
<a href="#">1757820-7</a>	NO						
<a href="#">1757820-8</a>	NO			CN5231-000, "AMP-0-1757820-8"			
<a href="#">1757820-9</a>	NO						
<a href="#">205089-1</a>	NO		A2160-ND	"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
<a href="#">205089-4</a>	NO						
<a href="#">205090-1</a>	NO		A2161-ND	"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			
<a href="#">205555-2</a>	NO			EF5284-000, "AMP-0-020555-2"			
<a href="#">205556-2</a>	NO						
<a href="#">205558-2</a>	NO						
<a href="#">205559-2</a>	NO						
<a href="#">205560-2</a>	NO						
<a href="#">205561-2</a>	NO						
<a href="#">205563-2</a>	NO						
<a href="#">205564-2</a>	NO						
<a href="#">862004-1</a>	NO						
<a href="#">866182-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1757819-0</a>	NO			CV0351-000, "AMP-1-1757819-0"			
<a href="#">1757819-6</a>	NO			CN5229-000, "AMP-0-1757819-6"			
<a href="#">1757819-7</a>	NO			EH2240-000, "AMP-0-1757819-7"			
<a href="#">1757819-9</a>	NO						
<a href="#">1757820-6</a>	NO			CN5230-000, "AMP-0-1757820-6"			
<a href="#">1757820-7</a>	NO						
<a href="#">1757820-9</a>	NO						
<a href="#">205089-1</a>	NO			"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
<a href="#">205089-4</a>	NO						
<a href="#">205090-1</a>	NO			"033-0012-00", "CC5846-000", "HD 20 SOCKET CONTACT", "4-16211-7507"			
<a href="#">205557-2</a>	NO						
<a href="#">862004-1</a>	NO						
<a href="#">866182-1</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205090-2</a>	NO						
<a href="#">205557-2</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205562-2</a>	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205090-2</a>	NO						
<a href="#">205557-2</a>	NO						
<a href="#">205562-2</a>	NO						