

# PRODUCT CHANGE NOTIFICATION (PCN)

Product Category POWER CONNECTORS **20210215-1**

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: 20210215

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Part collar manufacturing process is changing from extrusion to a stamped and formed design. All set screws are now internal hex key drive, previously some were slotted screws.

Discontinued  
Extrusion  
Version



Replacement  
Stamped and  
Formed  
Version



**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	3	15
Old product discontinuation date*	2021	5	31

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Compatibility Type	Replacement Part 1
CB35-36-CY	Direct	CBS35-36-C
CBA70-14-CY	Direct	CBS35-14-C
CS35-36SL-CY	Direct	CSS35-36-C
CSA70-14-CY	Direct	CSS35-14-C
CD35-36SL-QY	Direct	CDS35-36-Q
CO35-36SL-QY	Direct	COS35-36-Q