

# INFORMATION NOTE

N° 002/14

## Introduction of an improved carrier tape design affecting products in package PG-TQFP-48-6 and PG-TQFP-48-8

**Subject of Change:** Introduction of an improved carrier tape design affecting products in package PG-TQFP-48-6 and PG-TQFP-48-8.

**Products affected:** Please refer to 1\_cip00214 attached.

**Reason of Change:** Quality improvement

### Description of Change:

(for details please refer to 3\_cip00214 attached)

■ **Carrier Tape:**


#### Old

Tape design A16-C15  
Pocket without fence design



#### New

Tape design A16-C117  
Pocket with fence design



**Assessment:** The new carrier tape passed all tests.

**Time Schedule:** From June 2014 onwards.

### Documentation:

1\_cip00214 (products affected)

3\_cip00214 (additional information)

If you have any questions, please do not hesitate to contact your local Sales office.

**INF N°002/14**

Introduction of an improved carrier tape design affecting products in package PG-TQFP-48-6 and PG-TQFP-48-8



Sales Name	Current SP number	OPN	Package
SAF-XC886-6FFI 5V AC	SP000607048	XC8866FFI5VACFXUMA1	PG-TQFP-48-6
SAF-XC886-8FFI 5V AC	SP000607054	XC8868FFI5VACFXUMA1	PG-TQFP-48-6
SAF-XC886C-6FFA 5V AC	SP000607068	XC886C6FFA5VACFXUMA1	PG-TQFP-48-6
SAF-XC886C-6FFI 3V3 AC	SP000655548	XC886C6FFI3V3ACFXUMA1	PG-TQFP-48-6
SAF-XC886C-6FFI 5V AC	SP000607056	XC886C6FFI5VACFXUMA1	PG-TQFP-48-6
SAF-XC886CM-8FFI 5V AC	SP000607014	XC886CM8FFI5VACFXUMA1	PG-TQFP-48-6
SAF-XC886LM-6FFA 5V AC	SP000657428	XC886LM6FFA5VACFXUMA1	PG-TQFP-48-6
SAF-XC886LM-6FFI 5V AC	SP000607050	XC886LM6FFI5VACFXUMA1	PG-TQFP-48-6
SAF-XC886LM-8FFI 5V AC	SP000607052	XC886LM8FFI5VACFXUMA1	PG-TQFP-48-6
SAK-XC886-6FFA 5V AC	SP000210978	XC8866FFA5VACKXUMA1	PG-TQFP-48-6
SAK-XC886C-6FFA 5V AC	SP000607004	XC886C6FFA5VACKXUMA1	PG-TQFP-48-6
SAK-XC886C-8FFA 5V AC	SP000606668	XC886C8FFA5VACKXUMA1	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000558466	XC886C8RFA5VAAKXUMA2	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000627352	XC886C8RFA5VAAKXUMA4	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000674112	XC886C8RFA5VAAKXUMA8	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000674114	XC886C8RFA5VAAKXUMA9	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000706946	XC886C8RFA5VAAKXUMB2	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000706964	XC886C8RFA5VAAKXUMB3	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000763164	XC886C8RFA5VAAKXUMB5	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000763248	XC886C8RFA5VAAKXUMB6	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000786882	XC886C8RFA5VAAKXUMB7	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000798574	XC886C8RFA5VAAKXUMB8	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000803048	XC886C8RFA5VAAKXUMB9	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000824648	XC886C8RFA5VAAKXUMC1	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000839362	XC886C8RFA5VAAKXUMC2	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000840394	XC886C8RFA5VAAKXUMC3	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000842242	XC886C8RFA5VAAKXUMC4	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000878994	XC886C8RFA5VAAKXUMC5	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000994194	XC886C8RFA5VAAKXUMC7	PG-TQFP-48-6
SAK-XC886C-8RFA 5V AA	SP000994196	XC886C8RFA5VAAKXUMC6	PG-TQFP-48-6
SAK-XC886CLM-8FFA 5V AC	SP000606750	XC886CLM8FFA5VACKXUMA1	PG-TQFP-48-6
SAK-XC886CM-8FFA 3V3 AC	SP000607082	XC886CM8FFA3V3ACKXUMA1	PG-TQFP-48-6
SAK-XC886CM-8FFA 5V AC	SP000606964	XC886CM8FFA5VACKXUMA1	PG-TQFP-48-6
SAK-XC886LM-6FFA 5V AC	SP000606754	XC886LM6FFA5VACKXUMA1	PG-TQFP-48-6
SAK-XC886LM-8FFA 5V AC	SP000606752	XC886LM8FFA5VACKXUMA1	PG-TQFP-48-6
SAL-XC886CLM-8FFA 5V AC	SP000829526	XC886CLM8FFA5VACLXUMA1	PG-TQFP-48-6
SAL-XC886CM-8FFA 5V AC	SP000844270	XC886CM8FFA5VACLXUMA1	PG-TQFP-48-6
TLE7183QU	SP000868988	TLE7183QUXUMA1	PG-TQFP-48-8
TLE7183QU	SP000935748	TLE7183QUXUMA2	PG-TQFP-48-8
TLE7183QU	SP000959816	TLE7183QUXUMA3	PG-TQFP-48-8
TLE7183QU	SP000960560	TLE7183QUXUMA4	PG-TQFP-48-8