

| ISSUE DATE | FORECAST DATE | LAST TIME BUY | LAST TIME SHIP | NOTIFICATION NO. |
|---------------|---------------|-----------------|----------------|----------------------|
| 10 April 2020 | 01 July 2020 | 16 October 2020 | April 2021 | PCN-2020-04-10-01-IA |

This is to advise you that the following products will be discontinued.

PRODUCT ID: Industrial Application LCD Modules: Please see Table 1 on page 2 of this document for specific product numbers.

DESCRIPTION OF CHANGE:

Sharp is discontinuing the part numbers shown in Table 1. A Last Time Buy opportunity is being offered. However, a Last Time Buy Forecast is required to ensure quantity to meet Last Time Buy requirements.

See Table 1 for details. Forecast, Last Time Buy, and Last Time Ship dates are as shown above.

EFFECT OF CHANGE:

The LCD Modules in Table 1 are discontinued. All Last Time Buy purchases are NCNR (Non-cancellable, Non-returnable).

In case of further questions, please contact your Sharp Sales Representative.

| ISSUE DATE | FORECAST DATE | LAST TIME BUY | LAST TIME SHIP | NOTIFICATION NO. |
|---------------|---------------|-----------------|----------------|----------------------|
| 10 April 2020 | 01 July 2020 | 16 October 2020 | April 2021 | PCN-2020-04-10-01-IA |

Table 1: Affected Products

Status: Last Time Buy

| PART NUMBER | RECOMMENDED ALT. PART NUMBER** |
|--------------|--------------------------------|
| LQ035Q3DG01 | LQ035Q3DX01 |
| LQ035Q3DG03 | LQ035Q3DX01 |
| LQ035Q3DG05 | LQ035Q3DX01 |
| LQ035Q3DG06 | LQ035Q3DX01 |
| LQ035Q3DG07 | LQ035Q3DX01 |
| LQ035Q3DG12 | LQ035Q3DX01 |
| LQ035Q3DY01 | LQ035Q3DX01 |
| LQ043T1DG18 | LQ043T1DGxx |
| LQ043T1DG28 | LQ043T1DGxx |
| LQ043T1DG29 | LQ043T1DGxx |
| LQ043T1DG38 | LQ043T1DGxx |
| LQ043T1DG38G | LQ043T1DGxx |
| LQ043T1DG39 | LQ043T1DGxx |
| LQ043T1DG39G | LQ043T1DGxx |
| LQ043T1DH06 | LQ043T1DGxx |
| LQ070Y3DG1A | LQ070Y3LG05 |
| LQ070Y3DG3A | LQ070Y3LG05 |
| LQ070Y3DG3B | LQ070Y3LG05 |
| LQ070Y3DG3C | LQ070Y3LG05 |
| LQ070Y3LG02A | LQ070Y3LG05 |
| LQ070Y3LG04 | LQ070Y3LG05 |
| LQ070Y3LG4A | LQ070Y3LG05 |
| LQ070Y3LW01 | LQ070Y3LG05 |
| LQ080Y3LW01 | LQ080Y3LW01A |
| LQ104S1DG2C | N/A |

| PART NUMBER | RECOMMENDED ALT. PART NUMBER** |
|---------------|--------------------------------|
| LQ121S1DG81 | LQ121S1LG88 |
| LQ121S1DG82 | LQ121S1LG88 |
| LQ121S1LG79 | TBD |
| LQ121S1LG81 | LQ121S1LG88 |
| LQ121S1LG84 | LQ121S1LG88 |
| LQ121S1LG85 | LQ121S1LG88 |
| LQ121S1LG86 | LQ121S1LG88 |
| LQ150X1LW12 | LQ150X1LW95 |
| LQ150X1LW15 | LQ150X1LW95 |
| LQ156M1LG21/K | LQ156M3xxxx or N/A |
| LQ156M3LW01 | LQ156M3xxxx or N/A |
| LQ156M3LW01N | LQ156M3xxxx or N/A |
| LQ231U1LW31 | N/A |
| LQ231U1LW32 | N/A |
| LQ270M1LX01 | N/A |