



October 9, 2020

## Replacement of RP Plugs

Dear Valued Phihong Customer:

The current RP plugs are Not Recommended for New Designs and are due to be discontinued and will be replaced by the RP-AB01B-H plugs. The main difference between the plugs is the plastic material with the new versions having a higher flammability rating. The new RP plugs will change from material SABIC NORYL SE1 (UL94V-1), used in the current RP plugs, to Covestro FR6005/ Teijin MN-3600HS/ SABIC PC945 and meet UL94V-0.

Otherwise, form, fit and function are unchanged. The attached file titled "Clip Difference" indicates the markings between the current and new clips to differentiate them.

The current and replacement plugs are as follows:

<u>Current Model Number</u>	<u>New Model Number</u>
RPBAG(NC)-R	RPBAG-AB01B-H
RPA-R	RPA-AB01B-H
RPB-R	RPB-AB01B-H
RPC-R	RPC-AB01B-H
RPE-N-R	RPE-AB01B-H
RPH-R	RPH-AB01B-H
RPI-R	RPI-AB01B-H
RPK(NC)-R	RPK-AB01B-H
RPN-R	RPN-AB01B-H
RPS-N-R	RPS-AB01B-H

Sincerely,

Thomas Chin  
Sr. Marketing Manager  
Phihong USA Corp.