

Type of Notification:**To:** Sales

- | | | |
|---|--|-------------------------------------|
| <input type="checkbox"/> Product Change | <input type="checkbox"/> Process Change | <input type="checkbox"/> Relocation |
| <input type="checkbox"/> Product Alert | <input checked="" type="checkbox"/> Obsolescence | <input type="checkbox"/> Other |

Notification Date: August 5, 2013**Effective Date:** August 5, 2013AVX Part Number / Series / Product: 108557096008026

Customer Part Number / Series / Drawing: _____

Material Identification: _____

Date Code / Lot Code: _____

Applicable Information for Product Alerts:

Purchase Order Number: _____

Shipment Date: _____

Packing Slip Number(s): _____

Quantity: _____

Description of Advisory / Notice:

We can no longer produce 108557096008026 which is a right angle with 2.3mm tails. We can offer 108557096002026 which is a right angle with 3.0mm tails. We have not sold the -008026 in many years so this should not be an issue.

Point of Contact:**Name:** Tom Anderson**Title:** Product Manager**Address:** AVX Corporation**Telephone #:** 864-228-3421

1 AVX Boulevard

Fax #:

Fountain Inn, SC 29644

E-Mail: Tom.Anderson@avx.com