

## **TE Connectivity**

Product Change Notification: E-19-001091 PCN Date: 14-FEB-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| General Product Description: |
|------------------------------|
| HCR 150 & HCR 200 relays     |
|                              |

Description of Changes New winding machine

| Reason for Changes:                    |  |  |  |  |  |
|--|--|--|--|--|--|
| HCR Capacity Increase                  |  |  |  |  |  |
| Estimated Dates:                       |  |  |  |  |  |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only):             |  |  |  |  |
|  | 25-MAR-2019  |  |  |  |  |
| Last Ship Date (Obsolete Parts Only):  | Last Date for Mixed Shipments: (Changed Parts Only): |  |  |  |  |
|  | 29-APR-2019  |  |  |  |  |

## Part Number(s) being Modified:

| Part Number        | Part Discontinued<br>per PCN | Customer<br>Drawing | Customer Part<br>Number | Alias Part Number(s)          | Substitute Part<br>Number | Substitute Alias Part<br>Number(s) | Description Of<br>Difference |
|--------------------|------------------------------|---------------------|-------------------------|-------------------------------|---------------------------|------------------------------------|------------------------------|
| <u>1-1414476-0</u> | NO                           |                     |                         |                               |                           |                                    |                              |
| 1393315-2          | NO                           |                     |                         | "V23132A2001A200"             |                           |                                    |                              |
| <u>1393315-9</u>   | NO                           |                     |                         | "V23132B2002A200"             |                           |                                    |                              |
| <u>1416010-1</u>   | NO                           |                     |                         | "V23132-A2001-B200"           |                           |                                    |                              |
| 2-1414939-2        | NO                           |                     |                         | "V23132A2001B200-EV-<br>USBX" |                           |                                    |                              |
| <u>5-1414968-1</u> | NO                           |                     |                         | "V23132B2002B200-EV-<br>USBX" |                           |                                    |                              |
| <u>9-1415001-5</u> | NO                           |                     |                         | "CZ1474-000"                  |                           |                                    |                              |

## Part Number(s) being Modified:

| Part<br>Number | Part Discontinued<br>per PCN | Customer<br>Drawing | Customer Part<br>Number | Alias Part Number(s)          | Substitute Part<br>Number | Substitute Alias Part<br>Number(s) | Description Of<br>Difference |
|----------------|------------------------------|---------------------|-------------------------|-------------------------------|---------------------------|------------------------------------|------------------------------|
| 1-1414476-0    | NO                           |                     |                         |                               |                           |                                    |                              |
| 1393315-2      | NO                           |                     |                         | "V23132A2001A200"             |                           |                                    |                              |
| 1393315-9      | NO                           |                     |                         | "V23132B2002A200"             |                           |                                    |                              |
| 1416010-1      | NO                           |                     |                         | "V23132-A2001-B200"           |                           |                                    |                              |
| 2-1414939-2    | NO                           |                     |                         | "V23132A2001B200-EV-<br>USBX" |                           |                                    |                              |
| 5-1414968-1    | NO                           |                     |                         | "V23132B2002B200-EV-<br>USBX" |                           |                                    |                              |
| 9-1415001-5    | NO                           |                     |                         | "CZ1474-000"                  |                           |                                    |                              |