

# Product Discontinuation

2008-11-17

**OS-PD-2008-014**

Last order:	31.12.2010
Last delivery:	01.06.2011

Reason:

Discontinuation of GaN Technology at OSRAM OS due to portfolio adjustment.  
Please refer to products within appropriate package family according your application needs.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
<b>LB 3356</b>			3mm	No replacement			
LB 3356-JM-1-0-10-BULK	Q62703Q4192B200		3mm	No replacement			
LB 3356-K1N2-1-0-10-BULK	Q65110A2792		3mm	No replacement			
LB 3356-K2M1-1-0-10-BULK	Q65110A2790		3mm	No replacement			
LB 3356-L2N1-1-0-10-BULK	Q65110A2791		3mm	No replacement			
<b>LB A676</b>			SIDELED	No replacement			
LB A676-J2K2-1-0-10-R33-Z	Q65110A2265		SIDELED	No replacement			
LB A676-J2K2-1-0-10-R33-Z-SV	Q65110A0919		SIDELED	No replacement			
LB A676-J2L2-1-0-10-R33-Z	Q65110A2267		SIDELED	No replacement			
LB A676-K1-1-0-10-R33-Z-XX	Q65110A5313		SIDELED	No replacement			
LB A676-K1K2-1-0-10-R33-Z	Q65110A3706		SIDELED	No replacement			
LB A676-K1L1-1-0-10-R33-Z	Q65110A4293		SIDELED	No replacement			
LB A676-K1L1-1-0-10-R33-Z-DL	Q65110A5545		SIDELED	No replacement			
LB A676-K1L1-1-0-10-R33-Z-HE	Q65110A5020		SIDELED	No replacement			
LB A676-K1L2-1-0-10-R33-Z-B	Q62703Q4288B200		SIDELED	No replacement			
LB A676-K1L2-1-0-10-R33-Z-DL	Q62703Q4885B200		SIDELED	No replacement			
LB A676-K2-1-0-10-R33-Z-XX	Q65110A5314		SIDELED	No replacement			
LB A676-K2L1-1-0-10-R33-Z-SV	Q65110A0420		SIDELED	No replacement			
LB A676-K2L2-1-0-10-R33-Z	Q65110A2266		SIDELED	No replacement			
LB A676-K2L2-1-0-10-R33-Z-DL	Q62703Q4382B120		SIDELED	No replacement			
LB A676-K2L2-1-0-10-R33-Z-HE	Q65110A5026		SIDELED	No replacement			
LB A676-L1-1-0-10-R33-Z-XX	Q65110A5315		SIDELED	No replacement			
LB A676-L1L2-1-0-10-R33-Z-SV	Q65110A0651		SIDELED	No replacement			
LB A676-M1N1-1-0-10-R33-Z-DL	Q65110A8295		SIDELED	No replacement			
LB A676-M1N2-1-0-10-R33-Z	Q65110A5427		SIDELED	No replacement			
<b>LB M676</b>			Mini TOPLED	No replacement			
LB M676-J1K1-1-0-10-R18-Z	Q65110A4295		Mini TOPLED	No replacement			
LB M676-J1K1-1-0-10-R18-Z-BP	Q65110A4595		Mini TOPLED	No replacement			
LB M676-J1K1-1-0-10-R18-Z-HAR	Q65110A3292		Mini TOPLED	No replacement			
LB M676-J1K1-1-0-10-R18-Z-SV	Q65110A0922		Mini TOPLED	No replacement			
LB M676-J1K2-1-0-10-R18-Z	Q65110A2369		Mini TOPLED	No replacement			
LB M676-J1L2-1-0-10-R18-Z	Q65110A2371		Mini TOPLED	No replacement			
LB M676-J2K2-1-0-10-R18-Z	Q65110A2756		Mini TOPLED	No replacement			
LB M676-K1L1-1-0-10-R18-Z	Q65110A3261		Mini TOPLED	No replacement			
LB M676-K1L2-1-0-10-R18-Z	Q65110A2370		Mini TOPLED	No replacement			
LB M676-K1L2-1-0-10-R18-Z-HE	Q65110A5027		Mini TOPLED	No replacement			
LB M676-K2L1-1-0-10-R18-Z-DL	Q65110A5530		Mini TOPLED	No replacement			
LB M676-K2L2-1-0-10-R18-Z-SV	Q65110A3115		Mini TOPLED	No replacement			
<b>LB T676</b>			TOPLED	No replacement			
LB T676-F1G2-1-0-2-R18-Z	Q65110A5014		TOPLED	No replacement			
LB T676-G1H2-1-0-2-R18-Z-HE	Q65110A6118		TOPLED	No replacement			
LB T676-G1H2-1-0-2-R33-Z-HE	Q65110A5051		TOPLED	No replacement			
LB T676-J1K2-1-0-10-R18-Z	Q65110A4831		TOPLED	No replacement			
LB T676-J1K2-1-0-10-R18-Z-KS	Q65110A5123		TOPLED	No replacement			
LB T676-J1L2-1-0-10-R18-Z	Q65110A2130		TOPLED	No replacement			
LB T676-J2K2-1-0-10-R18-Z	Q65110A2159		TOPLED	No replacement			
LB T676-J2K2-1-0-10-R18-Z-H	Q65110A4695		TOPLED	No replacement			

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
LB T676-J2K2-1-0-10-R33-Z	Q65110A3707		TOPLED	No replacement			
LB T676-J2K2-1-0-10-R33-Z-SV	Q62703Q6445		TOPLED	No replacement			
LB T676-J2L2-1-0-10-R18-Z	Q65110A2161		TOPLED	No replacement			
LB T676-J2L2-1-0-10-R33-Z-B	Q62703Q4291B200		TOPLED	No replacement			
LB T676-K1-1-0-10-R18-Z-BP	Q65110A4651		TOPLED	No replacement			
LB T676-K1K2-1-0-10-R33-Z	Q65110A3212		TOPLED	No replacement			
LB T676-K1K2-1-0-10-R33-Z-DL	Q65110A5750		TOPLED	No replacement			
LB T676-K1K2-1-0-10-R33-Z-MM	Q65110A3770		TOPLED	No replacement			
LB T676-K1L1-1-0-10-R18-Z	Q65110A4296		TOPLED	No replacement			
LB T676-K1L1-1-0-10-R18-Z-JC	Q65110A5647		TOPLED	No replacement			
LB T676-K1L1-1-0-10-R33-Z-HAR	Q65110A3244		TOPLED	No replacement			
LB T676-K1L2-1-0-10-R18-Z-SV	Q65110A0926		TOPLED	No replacement			
LB T676-K1L2-1-0-10-R33-Z-HE	Q65110A5080		TOPLED	No replacement			
LB T676-K1L2-1-0-10-R33-Z-JC	Q65110A5648		TOPLED	No replacement			
LB T676-K1L2-1-0-10-R33-Z-SV	Q62703Q4573B200		TOPLED	No replacement			
LB T676-K2-1-0-10-R18-Z-BP	Q65110A4596		TOPLED	No replacement			
LB T676-K2-1-0-10-R18-Z-XX	Q65110A4965		TOPLED	No replacement			
LB T676-K2-1-0-10-R33-Z-MM	Q65110A3803		TOPLED	No replacement			
LB T676-K2L1-1-0-10-R18-Z	Q65110A4297		TOPLED	No replacement			
LB T676-K2L1-1-0-10-R33-Z-JCB	Q65110A4747		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R18-Z	Q65110A2160		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R18-Z-DL	Q65110A4684		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R18-Z-F	Q65110A1604		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R18-Z-MM	Q65110A3449		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-B	Q65110A0836		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-B	Q65110A5548		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-F	Q65110A2532		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-HE	Q65110A5028		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-JC	Q65110A4520		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-MM	Q65110A3771		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-SV	Q62703Q4574B200		TOPLED	No replacement			
LB T676-K2L2-1-0-10-R33-Z-SV	Q65110A0421		TOPLED	No replacement			
LB T676-L1-1-0-10-R18-Z-BP	Q65110A4652		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R18-Z	Q65110A4411		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R18-Z-B	Q65110A4653		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R18-Z-BP	Q65110A4597		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R18-Z-DLS	Q65110A4298		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R18-Z-JC	Q65110A5649		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R33-Z-DL	Q65110A5523		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R33-Z-HE	Q65110A5046		TOPLED	No replacement			
LB T676-L1L2-1-0-10-R33-Z-SV	Q65110A0278		TOPLED	No replacement			
LB T676-L2-1-0-10-R18-Z-BP	Q65110A4654		TOPLED	No replacement			
LB T676-M1-1-0-10-R18-Z-BP	Q65110A5985		TOPLED	No replacement			
LB T676-M1N1-1-0-10-R18-Z	Q65110A7076		TOPLED	No replacement			
LB T676-M1N2-1-0-10-R18-Z	Q65110A5428		TOPLED	No replacement			
LB T676-M1N2-1-0-10-R18-Z-SV	Q65110A6476		TOPLED	No replacement			
LB T676-M2-1-0-10-R18-Z-BP	Q65110A6217		TOPLED	No replacement			
LB T676-N1-1-0-10-R18-Z-BP	Q65110A6218		TOPLED	No replacement			
LB T676-N2-1-0-10-R18-Z-BP	Q65110A6219		TOPLED	No replacement			
<b>LB T776</b>				No replacement			
LB T776-F1G2-1-0-2-R18-Z-BP	Q65110A4599		TOPLED RG	No replacement			
LB T776-J2K2-1-0-10-R18-Z	Q65110A2226		TOPLED RG	No replacement			
LB T776-J2K2-1-0-10-R18-Z	Q65110A4044		TOPLED RG	No replacement			
LB T776-J2K2-1-0-10-R18-Z-BP	Q65110A4600		TOPLED RG	No replacement			
LB T776-J2L2-1-0-10-R18-Z	Q65110A2228		TOPLED RG	No replacement			
LB T776-K1L1-1-0-10-R18-Z-SV	Q65110A0422		TOPLED RG	No replacement			
LB T776-K2L2-1-0-10-R18-Z	Q65110A2227		TOPLED RG	No replacement			
LB T776-M1N2-1-0-10-R18-Z	Q65110A5429		TOPLED RG	No replacement			
<b>LATBT686</b>			Multi TOPLED	No replacement			
LATBT686-Q7-1+R-8+K9-1-20-R18-ZB-XX	Q65110A7125		Multi TOPLED	No replacement			
LATBT686-QR-1+RS-78+KL-1-20-R18-ZB	Q65110A2609		Multi TOPLED	No replacement			