

研華股份有限公司 Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Ruelguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com

IIoT Product Change Notice

The change will be applied on the ULI-238TS (BB-CANOP). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

Note: The ordering process has not been changed. Customers should continue to order model number BB-CANOP

1. Reason for the Change: Branding.

2. Affected Products: ULI-238TS (BB-CANOP)

3. Impact on Application: No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-238TS BB-CANOP	20BB250- 10741-00	1990038143T000 1990038142T000	Label	Old name plate TD Model CANOP RD B-B SMARTWORX Powered by ADANTECH advantech-bb.com CAN to CAN GND Isolated Repeater CAN_H CAN_L CAN_L CAN_H GND GND 10-30VDC advantech-bb.com	Branding



研華股份有限公司 Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Ruelguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com



5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-238TS (BB-CANOP)	ECOM-196350	12/15/2022	Running Change	Update name plate

^{*}Note: Cut-in progress depends on factory production schedule.

Contact Windows

PM	Brian Foster / <u>brian.foster@advantech.com</u>	
AE	N/A	

^{**} Note: The ordering process has not been changed. Customers should continue to order model number BB-CANOP