



Product Change Notification (PCN)

PCN Number	509106	Date Issued	June 19, 2020
Reason for Change	Obsolete		
Change Type Description	This is to inform you that the part(s) referenced in this notice will be made obsolete. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).		
Reason for Short Notice	Force Majeure		
Planned Implementation Date	June 30, 2020		
Recommended Replacement Parts	Please see the attached replacement parts list .xls file.		
Last Time Buy Date for Obsolete Parts	June 19, 2020		
Last Time Ship Date for Obsolete Parts	June 19, 2020		

RELEASED After Change

Overview

- This is to notify our customers that we are obsoleting the list of parts attached to this notification with replacement.
- The reason for this obsolescence is due to tool crash, and we will not be able to continue production OBS harnesses. Hence, we are obsoleting with immediate effect and no LTB date.
- Part Number Impact and replacement part
 - See attached parts list



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509106**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #	Replacement part #
509106	2138662433	2138652433
509106	2138662533	2138652533
509106	2138671633	2138651633
509106	2138672633	2138652633
509106	2138672733	2138652733
509106	2138672833	2138652833
509106	2138672933	2138652933
509106	2138671635	2138651635
509106	2138672635	2138652635
509106	2138671637	2138651637
509106	2138672637	2138651637
509106	2138682033	2138652033
509106	2146571603	2146551633
509106	2138672603	2146552633