



# Product Change Notification

## TE Connectivity

Product Change Notification: P-18-015510

PCN Date: 27-FEB-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change.

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from "Outside Vendor" to "Outside Vendor".

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard automotive requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. All FG part nrs should be entered into the document.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

01-MAY-2019

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1393774-0</a>	NO			"V23026A1003B201"			
<a href="#">1-1393774-2</a>	NO		PB284-ND	"V23026A1004B201"			
<a href="#">1-1393774-7</a>	NO			"V23026A1006B201"			
<a href="#">1393774-1</a>	NO		PB282-ND	"V23026A1001B201"			
<a href="#">1393774-8</a>	NO		PB283-ND	"V23026A1002B201"			
<a href="#">1393775-3</a>	NO			"V23026B1106B201"			
<a href="#">1393776-3</a>	NO			"V23026D1021B201 *X020"			
<a href="#">1393776-4</a>	NO			"V23026D1022B201 *X020"			
<a href="#">1393776-7</a>	NO			"V23026D1024B201 *X020"			
<a href="#">1393776-8</a>	NO			"V23026D1026B201 *X020"			
<a href="#">1393807-6</a>	NO			"V23154C 726B104"			
<a href="#">1393827-1</a>	NO			"V23154Z1021"			
<a href="#">1422015-8</a>	NO						
<a href="#">2-1393774-0</a>	NO			"V23026C1051B201"			
<a href="#">2-1393810-7</a>	NO			"V23154M 721B104", "V23154M0721B104"			
<a href="#">3-1393774-4</a>	NO			"V23026B1101B201"			
<a href="#">3-1393774-5</a>	NO			"V23026B1102B201"			
<a href="#">3-1393807-7</a>	NO			"V23154D 421B110", "CY2757-000", "AMP 3-1393807-7"			
<a href="#">3-1393810-8</a>	NO			"V23154M 726B104"			
<a href="#">4-1393809-4</a>	NO			"V23154D 726F104"			
<a href="#">4-1393817-4</a>	NO			"V23003B 37C410"			
<a href="#">5-1393808-4</a>	NO			"V23154D 717F104"			
<a href="#">8-1393806-6</a>	NO			"V23154C 721B104", "V23154C0721B104"			
<a href="#">9-1393809-1</a>	NO			"V23154Z1002"			
<a href="#">9-1393812-3</a>	NO			"V23054D1020F104"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1393774-2</a>	NO		PB284-ND	"V23026A1004B201"			
<a href="#">1393774-1</a>	NO		PB282-ND	"V23026A1001B201"			
<a href="#">1393774-8</a>	NO		PB283-ND	"V23026A1002B201"			
<a href="#">1393776-3</a>	NO			"V23026D1021B201 *X020"			
<a href="#">1393776-4</a>	NO			"V23026D1022B201 *X020"			
<a href="#">1393776-7</a>	NO			"V23026D1024B201 *X020"			
<a href="#">1393807-6</a>	NO			"V23154C 726B104"			
<a href="#">1393827-1</a>	NO			"V23154Z1021"			
<a href="#">2-1393774-0</a>	NO			"V23026C1051B201"			
<a href="#">2-1393810-7</a>	NO			"V23154M 721B104", "V23154M0721B104"			
<a href="#">3-1393774-4</a>	NO			"V23026B1101B201"			
<a href="#">3-1393807-7</a>	NO			"V23154D 421B110", "CY2757-000", "AMP-3-1393807-7"			
<a href="#">3-1393810-8</a>	NO			"V23154M 726B104"			
<a href="#">4-1393809-4</a>	NO			"V23154D 726F104"			
<a href="#">4-1393817-4</a>	NO			"V23003B 37C410"			
<a href="#">5-1393808-4</a>	NO			"V23154D 717F104"			
<a href="#">8-1393806-6</a>	NO			"V23154C 721B104", "V23154C0721B104"			
<a href="#">9-1393809-1</a>	NO			"V23154Z1002"			
<a href="#">9-1393812-3</a>	NO			"V23054D1020F104"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1393774-7</a>	NO			"V23026A1006B201"			
<a href="#">1393776-8</a>	NO			"V23026D1026B201 *X020"			
<a href="#">3-1393774-5</a>	NO			"V23026B1102B201"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1393774-0</a>	NO			"V23026A1003B201"			
<a href="#">1-1393774-7</a>	NO			"V23026A1006B201"			
<a href="#">1393775-3</a>	NO			"V23026B1106B201"			
<a href="#">1393776-8</a>	NO			"V23026D1026B201 *X020"			
<a href="#">1422015-8</a>	NO						
<a href="#">3-1393774-5</a>	NO			"V23026B1102B201"			