



Integrated Device Technology, Inc.  
 6024 Silver Creek Valley Road, San Jose, CA 95138  
 Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: FS-10-04

Last Buy Deadline for Submission of Order: 1-Aug-2011

Issue Date: 31-Jul-2010

Last Eligible Ship Date: 31-Oct-2011

Contact: Carl May  
 Title: Marketing Director - Standard Products  
 Phone #: 1-408-284-2718  
 Fax #: 1-408-284-1419  
 E-mail: [Carl.May@idt.com](mailto:Carl.May@idt.com)

**PRODUCT(S) AFFECTED:** **ATTACHMENT**  Yes  No

*(List Replacement Part #(s), if any)*

Selected Dual-Port and FIFO products will be discontinued.  
 Please see Attachment I for the discontinued part#.

**REASON FOR DISCONTINUANCE:**

- Replace slower speed with faster speed offerings  Other: \_\_\_\_\_
- Obsolete Fab Technology / Process \_\_\_\_\_
- Obsolete Assembly Technology / Process \_\_\_\_\_
- Obsolete Package / Material \_\_\_\_\_
- Declined Market

**CUSTOMER NOTIFICATION:**

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

***If you have any questions, please feel free to contact your local IDT distributor or sales representative.***

Customer: \_\_\_\_\_

E-Mail Address: \_\_\_\_\_

Name/Date: \_\_\_\_\_

Phone#: \_\_\_\_\_

Title: \_\_\_\_\_

Fax# : \_\_\_\_\_

**CUSTOMER COMMENTS:** \_\_\_\_\_

**IDT ACKNOWLEDGEMENT:**

Received By: \_\_\_\_\_

Date: \_\_\_\_\_



Integrated Device Technology, Inc.  
 6024 Silver Creek Valley Road, San Jose, CA 95138  
 Phone #: (408) 284-8200

## PRODUCT DISCONTINUANCE NOTICE (PDN)

### ATTACHMENT I - PDN #: FS-10-04

#### Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
70P27L12PFG	None	723614L20PF8	None
70P27L12PFG8	None	723614L20PFI	None
70P27L15PFGI	None	723614L20PFI8	None
70P27L15PFGI8	None	723614L20PQF	None
723611L15PF	None	723614L20PQFI	None
723611L15PF8	None	72T20118L10BB	None
723611L15PQF	None	72T20118L4BB	None
723611L20PF	None	72T20118L5BB	None
723611L20PF8	None	72T20118L6-7BB	None
723611L20PFI	None	72T2098L10BB	None
723611L20PFI8	None	72T2098L4BB	None
723611L20PQF	None	72T2098L5BB	None
723611L20PQFI	None	72T2098L6-7BB	None
723612L15PF	None	72T40108L10BB	None
723612L15PF8	None	72T40108L4BB	None
723612L15PQF	None	72T40108L5BB	None
723612L15PQFG	None	72T40108L6-7BB	None
723612L20PF	None	72T40118L10BB	None
723612L20PF8	None	72T40118L4BB	None
723612L20PFI	None	72T40118L4BBG	None
723612L20PFI8	None	72T40118L5BB	None
723612L20PQF	None	72T40118L6-7BB	None
723612L20PQFI	None	72T40118L6-7BBI	None
723613L15PF	None	72T51248L5BB	None
723613L15PF8	None	72T51248L6-7BB	None
723613L20PF	None	72T51248L6-7BBI	None
723613L20PF8	None	72T51258L5BB	None
723613L20PFI	None	72T51258L6-7BB	None
723613L20PFI8	None	72T51258L6-7BBI	None
723613L20PQF	None	72T54262L5BB	None
723613L20PQFI	None	72T54262L5BBG	None
723614L15PF	None	72T54262L6-7BB	None
723614L15PF8	None	72T54262L6-7BBG	None
723614L15PQF	None	72T54262L6-7BBI	None
723614L20PF	None		