

Product Change Notification (PCN)

PCN Number	501796	Date Issued	December 01, 2016
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	New Capacity		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	March 08, 2017		
Sample Availability Date (Changed Part)	March 08, 2017		
Planned Implementation Date	April 07, 2017		
Method of Identifying Change	Product made after planned implementation date can contain the change		

RELEASED

After Change

Overview

- Molex will be adding a MX150 Receptacle Mat Seal Tin Terminal capacity tool to support increasing demand
 - No change to fit, form, function
 - PPAP will be available upon request
- Assembly Part Numbers Affected
 - 33012-xxxx
 - 34780-xxxx
 - For cable & harness assemblies see attached impact report



1 Molex Confidential Information
© 2016 Molex - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

molex

Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501796**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

330122001

330122002

330122003

330122004

330122021

330122021

330122022

330122023

330123001

330123002

330123003

330123004

330123021