



## Product Change Notification - SYST-24QMCA773

---

**Date:**

25 Oct 2018

**Product Category:**

USB Products

**Affected CPNs:****Notification subject:**

Data Sheet - USB82642 Automotive USB 2.0 Hub and Flash Media Card Controller Combo Data Sheet Document Revision

**Notification text:**

SYST-24QMCA773

Microchip has released a new DeviceDoc for the USB82642 Automotive USB 2.0 Hub and Flash Media Card Controller Combo of devices. If you are using one of these devices please read the document located at [USB82642 Automotive USB 2.0 Hub and Flash Media Card Controller Combo](#).

**Notification Status:** Final

**Description of Change:**

- 1) Corrected Section 6.1, "Pin Reset States" in TABLE 6-2: Pin SPI\_DO/SDA\_EP/SPI\_SPD\_- SEL
- 2) Removed Section 7.5.6, "In-Circuit EEPROM Programming";

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 25 Oct 2018

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):**

[USB82642 Automotive USB 2.0 Hub and Flash Media Card Controller Combo](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

SYST-24QMCA773 - Data Sheet - USB82642 Automotive USB 2.0 Hub and Flash Media Card  
Controller Combo Data Sheet Document Revision

Affected Catalog Part Numbers(CPN)

- USB82642AM-A-000528-V02
- USB82642AM-H-000728-V05
- USB82642AM-H-000728-V09
- USB82642AMR-A-000528-V02
- USB82642AMR-A-000528V10
- USB82642AMR-H-000728-V05
- USB82642AMR-H-000728-V09