



Product Change Notification

TE Connectivity


Product Change Notification: P-16-013906

PCN Date: 01-DEC-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Change of marking method at SR4 and SR6 relays.

Description of Changes
In order to continuous product improvement, we change the printing method on SR4 and SR6 relays from tampo print to laser printing. By that, the printing of especially the small characters is sharper, the change of types in production is easier and faster and the production quantity output can be improved. Furthermore, the production date code can be printed on top also and is therefore easier to read. All data specified in datasheet and approvals keep unchanged.



Reason for Changes:	
Product improvement.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	13-MAR-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	08-SEP-2017

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415017-1	NO			"V23050-A1024-A551", "V23050A1024A551"			
1415054-1	NO			"SR4M4021"			
1415055-1	NO			"SR4D4012"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415055-1	NO			"SR4D4024"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1415033-1	NO			"SR6ZB024"			
6-1415027-1	NO			"SR6D4024"			
6-1415054-1	NO			"SR4M4110"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415053-1	NO			"SR4M4012"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			
9-1415537-4	NO			"SR6C6K24"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
4393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
4393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415017-1	NO			"V23050-A1024-A551", "V23050A1024A551"			
1415054-1	NO			"SR4M4021"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415055-1	NO			"SR4D4024"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
5-1415033-1	NO			"SR6ZB024"			
6-1415027-1	NO			"SR6D4024"			
6-1415054-1	NO			"SR4M4110"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415053-1	NO			"SR4M4012"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			
9-1415537-4	NO			"SR6C6K24"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
4393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
4393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1415017-1	NO			"V23050-A1024-A551", "V23050A1024A551"			
1-1415054-1	NO			"SR4M4021"			
1-1415055-1	NO			"SR4D4012"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415055-1	NO			"SR4D4024"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
5-1415033-1	NO			"SR6ZB024"			
6-1415027-1	NO			"SR6D4024"			
6-1415054-1	NO			"SR4M4110"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-8	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415053-1	NO			"SR4M4012"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1415053-1	NO			"SR4M4024"			
5-1415033-1	NO			"SR6ZB024"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1415053-1	NO			"SR4M4024"			
5-1415033-1	NO			"SR6ZB024"			