
End of Life Notification EOL18.018

Fixed Wavelength DWDM XFP

FTLX3613M3xx FTLX3813x3xx FTLX3912x3xx Variants

This document is an End of Life Notification (EOL) for Finisar’s variant DWDM XFP transceivers.

Affected Part Numbers and Recommended Replacement Part Numbers

The Finisar part numbers affected by this EOL notice are as follows:

Finisar EOL Part Number	Suggested Replacement
FTLX3613M3xx	None
FTLX3613M3xx-xx	None
FTLX3813F3xx	None
FTLX3813F3xx-xx	None
FTLX3813M3xx	None
FTLX3813M3xx-xx	None
FTLX3912M3xx	None
FTLX3912M3xx-xx	None
FTLX3912M3xxP-xx	None

Reason for Discontinuation

Broadcom EOL 10G EML TOSA manufactured at their facility in Mexico.

End of Life Dates

All last time buy purchase orders must be received by July 4th, 2018.

The last time shipment date will be December 31st, 2018, or earlier.

Order Acceptance/Change Conditions

Any orders for the discontinued products listed above with a requested ship date after July 4th, 2018 will be non-cancelable and non-returnable (NCNR). The words “non-cancelable, non-returnable” must be clearly indicated on these orders. These orders cannot be changed, rescheduled, or cancelled.

RMA Replacements

After July 4th, 2018, Finisar reserves the right to replace any of the discontinued products listed above returned under RMA (Return Material Authorization) with either the suggested replacement part or with a credit, at Finisar’s discretion.

We apologize in advance for any inconvenience this may cause. Please do not hesitate to call on your local distributor, rep, or local Finisar sales manager for any additional information you need.

For More Information

Finisar Corporation
1389 Moffett Park Drive
Sunnyvale, CA 94089-1134
Tel. (408) 548-1000
Fax (408) 541-6138
sales@finisar.com
www.finisar.com