

Date: May 21, 2013

PCN- 27142

Product Change Notification

Change Title:

REVISE OVERALL CABLE LENGTH TOLERANCES FOR 3.5MM PLUGS

Product (s) Affected:

32HR***32X SERIES, 32HR***84X SERIES, 33HR***33X SERIES, 33HR***84X SERIES,
35HR***35X SERIES, 35HR***84X SERIES, 35HR***90X SERIES,
36HR***35X SERIES, 36HR***36X SERIES, 36HR***84X SERIES,

4C7305X, 4C7828X, 4C8096X, 4C8188X, 4C8190AX, 4C8273X, 4C8311, 4C8391, 4C8395

Reason for Change:

MANUFACTURING PROCESS CHANGES.

Description of Change:

3" LONG +/-0.4", 4"-6" LONG +/-0.6", 9"-10" LONG +/-0.8", 12"-22" LONG +/-1.2",
24"-36" LONG +/-1.6", 48"-78" LONG +/-2.0", 118"-180" LONG +/-4.0", 240"-600" LONG +/-5.0"
1200" LONG +/-9"

Estimated Schedule of Change:

JUNE 2013

Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____

Signature

Print

(Electronic Signature is acceptable)

Company: _____

Location: _____

Title: _____

Date: _____

Please return the signed PCN form to the attention of:

Switchcraft Customer Service Department

jpulliam@switchcraft.com

FAX: 773-792-2129