



Not Recommended for New Design: DQ Series Relays

NRFND.PG0004.12.26.2018

12.26.2018

About This Notice:	The DQ Series Relays have changed status to Not Recommended For New Design due to possible plans for discontinuation in the future.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	See attached. The closest substitute would be the DZ-S Series Relay which is not a drop-in replacement.
Datasheet(s):	See attached.
Notes:	