

# HellermannTyton

August 28, 2017

Re: Bushing Change Notification

To Our Valued Customer:

DIGI-KEY CORPORATION

ATTN: Becca Stenseth, Lynnette Kinsman, and Marc Kaluza

To better serve your business, we inform you of the following change.

The current coating for the bushing is being replaced with a new coating. This new coating will be more environmentally friendly while keeping the integrity of the product's performance.

The following HellermannTyton part number(s) will no longer be available and will be replaced with the new HellermannTyton part number(s).

Current HT Part Number	New HT Part Number	Customer Part Number
151-00756	151-02104	1436-1812-ND
151-01105	151-02099	151-01105-ND
HDM320BHIHSUVC2	151-02098	1436-1408-ND
HDM320BHIHSUVH4	151-02094	HDM320BHIHSUVH4-ND
HDM400BHIHSUVH4	151-01224	HDM400BHIHSUVH4-ND

The last day to purchase the current HellermannTyton part number is December 31<sup>st</sup> \*\*. Beginning January 1<sup>st</sup>, we ask that orders be placed for the new HellermannTyton part number. Any open orders will be revised to the new part number.

We ask that you acknowledge this notification within 10 business days. Please let us know if you approve of the change or need additional information. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative.

We appreciate your support in this change and thank you for your continued business.

Sincerely,

Kelsey Shrader  
Quality Project Engineer  
Office: 414 355 1130 x 8751  
Email: [kshrader@htamericas.com](mailto:kshrader@htamericas.com)

\*\*Subject to change based on availability.