

PRODUCT CHANGE NOTIFICATION

#PCN-ICC-HL1H-15

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ICC	BE1	Mechanical	Notify Distributors and Field	2/2/2015

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description of Change:

Housing of the fuse lever has been slightly modified due to production reasons. Small hinges had been removed and ribs added at the opposite side (fuse carrier). Function is not affected. More solidly defined snap-in available now. Old and new versions are still being produced and can be used together.

Warranty Information:

Stock Status

Can existing stock still be used? Y


Is mixture of stock acceptable? Y

Transaction Dates:

Date modification goes into effect from Germany: 1/1/2015

Expected first shipment (from Phoenix Contact) of the modified product(s): 3/2/2015

PRODUCT CHANGE NOTIFICATION



Should you have any issues with the timeline or content of this change, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:

ALAN SAPPE'
Senior Product Marketing Specialist
(717)944-1300x3386
asappe@phoenixcon.com

Thank you,



BILL SCHALON, Product Marketing Manager

Part#	Type Description
3004100	UK 5-HESI
3004126	UK 5-HESILED 24
3004142	UK 5-HESILA 250