



Product Change Notification

PCN#: FIBER CABLE, CONNECTORS- 2017-11-03 Issue Date: 07Nov2017

Impacted Regions: NA EMEA LATAM AP

Reason for Change: Discontinuation Other OBS & Replace

DESCRIPTION OF CHANGE: *(Not required for discontinuation)*

The original Panduit OptiCam tool (the OCTT), plus related kits, are being discontinued in favor of the OptiCam 2 tool. The OptiCam 2 performs the same “cam” function for the termination of all Panduit OptiCam and OptiCam 2 connectors while also providing a calculated insertion loss value. This is a superior functionality versus the older tool’s VFL test. Please note that the OptiCam 2 does not include a VFL function, as it uses a non-visible laser.

PHOTOS/DRAWING *(where applicable)*

IMPACTED PART NUMBERS AND REPLACEMENT (where applicable) PART NUMBERS:
FCAMKIT, FPPKIT-CVY, OCTT, FIELDKITUPG, FPPKIT-CVY-K (see page 2)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

Schedule for Change	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2017	11	03
Old product discontinuation date*	2018	02	03

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

CUSTOMER SERVICE CONTACTS:

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CustomerService@panduit.com	CHINA: 800-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed Line) 000 800 6500369 (Mobile) IND-customer_service@panduit.com	INDONESIA: 001 803 65 7571 SGP-customer_service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA: 1800 801435 SGP-customer_service@panduit.com	SINGAPORE: 1-800-7263848 SGP-CUSTOMER_SERVICE@panduit.com	
	TAIWAN: 0080 165 1487 SGP-CUSTOMER_SERVICE@panduit.com	THAILAND: 001-800-65-6385 SGP-customer_service@panduit.com		
LATIN AMERICA	BRAZIL: 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000, X80520 01 800 360 86 00 (Toll Free) mex-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
	NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA EMEA-CustomerServices@panduit.com Phone: +44 208 6017219	

To add a contact or to unsubscribe, please send an e-mail to PCN@panduit.com

