



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-128401

PCN Date: 17-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Heat Shrink Tubing Stick (-STK) products

Description of Changes
This PCN is to inform customers of changes to the packaging of the boxes used for the Heat Shrink Tubing products supplied in the Stick format (-STK, 1.2metre/4ft lengths). For more clarification check reference attachments

Reason for Changes:

PCN Attributes:	
Product Category: Heat Shrink Tubing	Kind of Change: Packaging Type
Change Feature: Bulk	Potential Customer Impact: No Customer Impact
Remarks: The new packaging is to improve the robustness of the packaging during transportation and storage. It moves away from the square cross section boxes to a more rectangular cross section. This gives greater stability when boxes are stacked and improves the strength of the boxes.	

Estimated Dates:	
Last Order Date (Obsolete Parts Only): 03-FEB-2022	First Ship Date of Changed Items (Changed Parts Only): 03-FEB-2022
Last Ship Date of Changed Items (Obsolete Parts Only): 03-FEB-2022	Last Date for Mixed Shipments: (Changed Parts Only): 03-FEB-2022
Effectivity Date: 03-FEB-2022	Date of First Samples: 03-FEB-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0879832001	NO			"1190648-8", "RPPM-16/4-X-STK"			
1074372007	NO			"7-1190784-1", "DWTC-8/2-X-STK"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
2525592005	NO			"4-1191848-8", "RBK-ILS-125-NR1-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5039572011	NO			"6-1193803-4", "TPEM-NR7-0-STK"			
5039822001	NO			"1-1193804-1", "TPEM-NR6-0-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
7501712002	NO			"3-1195850-1", "RBK-ILS-125-NR4-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
8503232002	NO			"9-1196629-6", "DWTC-12/3-X-STK"			
8953152001	NO			"1196962-3", "RPPM-12/3-X-STK"			
9556822004	NO			"1-1197399-8", "DWTC-4/1-X-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CH03642001	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
CV20922001	NO			"RW-175-E-3/64-X-STK"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25382001	NO			"RW-175-E-3/32-X-STK", "5-1899810-1"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV25902001	NO			"RW-175-E-1/2-X-STK", "4-1899810-8"			
CV37312001	NO			"RW-175-E-3/4-X-STK", "3-1899810-9"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			
EL84962001	NO			"RBK-VWS-125-NR3-X-STK", "8-1899840-6"			
EL88602001	NO			"RBK-VWS-125-NR2-X-STK", "9-1899840-9"			
EL91232001	NO			"PROV-VERSAFIT-3/64-0-STK", "1-1899841-8"			
NB07402001	NO			"HTAT-12/3-0-STK", "1899848-1"			
NB07552001	NO			"HTAT-16/4-0-STK"			
NB07752001	NO			"HTAT-24/6-0-STK"			
NB07892001	NO			"HTAT-32/8-0-STK"			
NB08012001	NO			"HTAT-4/1-0-STK"			
NB08082001	NO			"HTAT-48/13-0-STK"			
NB08192001	NO			"HTAT-8/2-0-STK"			
NB09012001	NO						
NB09282001	NO						
NB09312001	NO			"ATUM-12/4-0-STK"			
NB09542001	NO			"ATUM-16/4-0-STK"			
NB09662001	NO						
NB09952001	NO			"ATUM-19/6-0-STK"			
NB10132001	NO						
NB10372001	NO			"ATUM-24/8-0-STK"			
NB10572001	NO						
NB10602001	NO						
NB10802001	NO						
NB10892001	NO						
NB11022001	NO						
NB11212001	NO						
NB11242001	NO			"ATUM-40/13-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM-6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB13892001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB13942001	NO						
NB13982001	NO						
NB14002001	NO						
NB14032001	NO						
NB14062001	NO						
NB14832001	NO						
NB14862001	NO						
NB14882001	NO						
NB14902001	NO						
NB14912001	NO						
NB14932001	NO						
NB15292001	NO						
NB15412001	NO						
NB16212001	NO						
NB16282001	NO			"RW-175-1/2-X-STK"			
NB16412001	NO						
NB16502001	NO			"RW-175-3/16-X-STK"			
NB16572001	NO						
NB16622001	NO						
NB16702001	NO			"RW-175-3/8-X-STK"			
NB17002001	NO						
NB17042001	NO						
NB17372001	NO			"RP-4800-NO.2-0-STK"			
NB17632001	NO						
NB17662001	NO						
NB17872001	NO			"RW-175-1-X-STK"			
NB17902001	NO			"RW-175-3/4-X-STK"			
NB24322001	NO						
NB25752001	NO						
NB25802001	NO						
NB25822001	NO			"SCL-1/8-0-STK"			
NB25842001	NO			"SCL-3/8-0-STK"			
NB25862001	NO			"SCL-3/16-0-STK"			
NB25882001	NO			"SCL-1/2-0-STK"			
NB25922001	NO						
NB25942001	NO			"SCL-1-0-STK"			
NB25962001	NO			"SCL-1/4-0-STK"			
NB34372001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2525592005	NO			"4-1191848-8", "RBK-ILS-125-NR1-0-STK"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CV20922001	NO			"RW-175-E-3/64-X-STK"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			
NB07752001	NO			"HTAT-24/6-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0879832001	NO			"1190648-8", "RPPM-16/4-X-STK"			
1074372007	NO			"7-1190784-1", "DWTC-8/2-X-STK"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
2525592005	NO			"4-1191848-8", "RBK-ILS-125-NR1-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5039572011	NO			"6-1193803-4", "TPEM-NR7-0-STK"			
5039822001	NO			"1-1193804-1", "TPEM-NR6-0-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
7501712002	NO			"3-1195850-1", "RBK-ILS-125-NR4-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			
8503232002	NO			"9-1196629-6", "DWTC-12/3-X-STK"			
8953152001	NO			"1196962-3", "RPPM-12/3-X-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CH03642001	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
CV20922001	NO			"RW-175-E-3/64-X-STK"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25382001	NO			"RW-175-E-3/32-X-STK", "5-1899810-1"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV25902001	NO			"RW-175-E-1/2-X-STK", "4-1899810-8"			
CV37312001	NO			"RW-175-E-3/4-X-STK", "3-1899810-9"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			
EL84962001	NO			"RBK-VWS-125-NR3-X-STK", "8-1899840-6"			
EL88602001	NO			"RBK-VWS-125-NR2-X-STK", "9-1899840-9"			
NB07402001	NO			"HTAT-12/3-0-STK", "1899848-1"			
NB07552001	NO			"HTAT-16/4-0-STK"			
NB07752001	NO			"HTAT-24/6-0-STK"			
NB07892001	NO			"HTAT-32/8-0-STK"			
NB08012001	NO			"HTAT-4/1-0-STK"			
NB08082001	NO			"HTAT-48/13-0-STK"			
NB08192001	NO			"HTAT-8/2-0-STK"			
NB09662001	NO						
NB10132001	NO						
NB10892001	NO						
NB13892001	NO						
NB17002001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB17042001	NO						
NB17662001	NO						
NB17872001	NO			"RW-175-1-X-STK"			
NB17902001	NO			"RW-175-3/4-X-STK"			
NB25752001	NO						
NB25802001	NO						
NB25822001	NO			"SCL-1/8-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0879832001	NO			"1190648-8", "RPPM-16/4-X-STK"			
1074372007	NO			"7-1190784-1", "DWTC-8/2-X-STK"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
2525592005	NO			"4-1191848-8", "RBK-ILS-125-NR1-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5039572011	NO			"6-1193803-4", "TPEM-NR7-0-STK"			
5039822001	NO			"1-1193804-1", "TPEM-NR6-0-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
7501712002	NO			"3-1195850-1", "RBK-ILS-125-NR4-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			
8503232002	NO			"9-1196629-6", "DWTC-12/3-X-STK"			
8953152001	NO			"1196962-3", "RPPM-12/3-X-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CH03642001	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
CV20922001	NO			"RW-175-E-3/64-X-STK"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25382001	NO			"RW-175-E-3/32-X-STK", "5-1899810-1"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV25902001	NO			"RW-175-E-1/2-X-STK", "4-1899810-8"			
CV37312001	NO			"RW-175-E-3/4-X-STK", "3-1899810-9"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EL84962001	NO			"RBK-VWS-125-NR3-X-STK", "8-1899840-6"			
EL88602001	NO			"RBK-VWS-125-NR2-X-STK", "9-1899840-9"			
NB07402001	NO			"HTAT-12/3-0-STK", "1899848-1"			
NB07552001	NO			"HTAT-16/4-0-STK"			
NB07752001	NO			"HTAT-24/6-0-STK"			
NB07892001	NO			"HTAT-32/8-0-STK"			
NB08012001	NO			"HTAT-4/1-0-STK"			
NB08082001	NO			"HTAT-48/13-0-STK"			
NB08192001	NO			"HTAT-8/2-0-STK"			
NB09662001	NO						
NB10132001	NO						
NB10892001	NO						
NB13892001	NO						
NB17002001	NO						
NB17662001	NO						
NB17872001	NO			"RW-175-1-X-STK"			
NB17902001	NO			"RW-175-3/4-X-STK"			
NB25752001	NO						
NB25802001	NO						
NB25822001	NO			"SCL-1/8-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB09542001	NO			"ATUM-16/4-0-STK"			
NB14882001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9556822004	NO			"1-1197399-8", "DWTC-4/1-X-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
9556822004	NO			"1-1197399-8", "DWTC-4/1-X-STK"			
EL91232001	NO			"PROV-VERSAFIT-3/64-0-STK", "1-1899841-8"			
NB07552001	NO			"HTAT-16/4-0-STK"			
NB09012001	NO						
NB09282001	NO						
NB09312001	NO			"ATUM-12/4-0-STK"			
NB09542001	NO			"ATUM-16/4-0-STK"			
NB09952001	NO			"ATUM-19/6-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10372001	NO			"ATUM-24/8-0-STK"			
NB10572001	NO						
NB10602001	NO						
NB10802001	NO						
NB11022001	NO						
NB11212001	NO						
NB11242001	NO			"ATUM-40/13-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM-6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB13942001	NO						
NB13982001	NO						
NB14002001	NO						
NB14032001	NO						
NB14062001	NO						
NB14832001	NO						
NB14862001	NO						
NB14882001	NO						
NB14902001	NO						
NB14912001	NO						
NB14932001	NO						
NB15292001	NO						
NB15412001	NO						
NB16212001	NO						
NB16282001	NO			"RW-175-1/2-X-STK"			
NB16412001	NO						
NB16502001	NO			"RW-175-3/16-X-STK"			
NB16572001	NO						
NB16622001	NO						
NB16702001	NO			"RW-175-3/8-X-STK"			
NB17002001	NO						
NB17372001	NO			"RP-4800-NO.2-0-STK"			
NB17632001	NO						
NB24322001	NO						
NB25822001	NO			"SCL-1/8-0-STK"			
NB25842001	NO			"SCL-3/8-0-STK"			
NB25862001	NO			"SCL-3/16-0-STK"			
NB25882001	NO			"SCL-1/2-0-STK"			
NB25922001	NO						
NB25942001	NO			"SCL-1-0-STK"			
NB25962001	NO			"SCL-1/4-0-STK"			
NB34372001	NO						