



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-143739

PCN Date: 14-JUL-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Terminal Contacts

Description of Changes
Please be aware that the packaging reel is being changed for the following mentioned part numbers. Please refer to attached document for details.
Other attachments:
[Reference Document](#)

Reason for Changes:

PCN Attributes:	
Product Category: Terminals	Kind of Change: Packaging Type
Change Feature: Reel	Potential Customer Impact: No Customer Impact
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only): 03-OCT-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160533-1	NO						
160534-1	NO						
2238045-2	NO						
342368-1	NO			"CU3083-000", "AMPS-0-0342368-1"			
41202	NO						
41274	NO						
41274-1	NO						
41330	NO			"668-1036-02"			
41332	NO						
41333	NO						
41559	NO						
41771-1	NO						
42100-2	NO						
42400-1	NO						
42801-1	NO						
60197-1	NO						
61283-1	NO			"0-0061283-1"			
61436-1	NO						
61481-1	NO						
63306-1	NO						
63475-2	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
63477-2	NO						
640051-1	NO						
640052-1	NO						
640253-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160534-1	NO						
342368-1	NO			"CU3083-000", "AMPS-0-0342368-1"			
41202	NO						
42400-1	NO						
63475-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160534-1	NO						
2238045-2	NO						
342368-1	NO			"CU3083-000", "AMPS-0-0342368-1"			
41202	NO						
41274-1	NO						
41333	NO						
41559	NO						
42400-1	NO						
60197-1	NO						
61283-1	NO			"0-0061283-1"			
61481-1	NO						
63475-2	NO						
63477-2	NO						
640051-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160534-1	NO						
2238045-2	NO						
342368-1	NO			"CU3083-000", "AMPS-0-0342368-1"			
41202	NO						
41274-1	NO						
41333	NO						
41559	NO						
42400-1	NO						
60197-1	NO						
61283-1	NO			"0-0061283-1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
61481-1	NO						
63475-2	NO						
63477-2	NO						
640051-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
41274	NO						
41333	NO						
42100-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160533-1	NO						
41202	NO						
41274	NO						
41274-1	NO						
41330	NO			"668-1036-02"			
41332	NO						
41333	NO						
41559	NO						
41771-1	NO						
42100-2	NO						
42400-1	NO						
42801-1	NO						
60197-1	NO						
61436-1	NO						
61481-1	NO						
63306-1	NO						
63475-2	NO						
640051-1	NO						
640052-1	NO						
640253-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
160534-1	NO						
342368-1	NO			"CU3083-000", "AMPS-0-0342368-1"			



Paper reel change from 999225-1 to 2400473-1






EVERY CONNECTION COUNTS



Paper reel appearance status 999225-1 & 2400473-1




Before

Reel part	Reel status	Fixed method	Different
995225-1	 		<ol style="list-style-type: none"> 1. No hole 2. Fixed of FIBER TAPE

Note:

1. Paper core status is different
2. Fixed method is different
3. Flag have small change, two side the circular hole change to the rectangle hole

After

Reel part	Reel status	Fixed method	Different
2400473-1	 		<ol style="list-style-type: none"> 1. Hole on the core 2. Fixed of core hole



Thanks