

PRODUCT DISCONTINUATION NOTICE

PDN Number: 18-0612A Date Issued: June 12, 2018

Series: Standard SMT PLCC socket, 52 position, tube packaged

Discontinued Part Number: 940-44-052-17-400000

Reason for discontinuation: No longer available packaged in tubes. This part will continue to be available packaged on tape and reel, see table below for alternative part number.

Effective Date: Immediate

Last Time Buy Date: Available until stock is depleted

| Affected Part Numbers | |
|--|--|
| Discontinued Part Number (Tube packaged) | Alternative Part Number (Tape & Reel packaged) |
| 940-44-052-17-400000 | 940-44-052-17-400004 |

Contact Information: Contact Mill-Max sales at sales@mill-max.com for any questions about this notice.

Disclaimer: Review this notice in its entirety and ensure that this change is not detrimental to your application. While Mill-Max takes precautions to make Product Changes as faultless as possible, only you, the Customer, know your specific application. Review this change with respect to your application. Contact us if you have questions or concerns. Request samples (if available). Mill-Max will make every attempt to support you through this change.